



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 7853D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT SHOCK ABSORBER RH	NOT NECESSARY	324.00	-
1	FRONT SHOCK ABSORBER MOUNTING RH	NOT NECESSARY	95.00	-
1	FRONT LOWER ARM RH	BENT	644.60	545.00
1	FRONT KNUCKLE ARM RH	DAMAGED	285.10	285.10
1	FRONT KNUCKLE ARM BEARING RH	DAMAGED	346.60	346.60
1	FRONT LINKAGE RH	NOT NECESSARY	92.40	-
1	FRONT STEERING TIE ROD END RH	NOT NECESSARY	91.20	-
2	FRONT HEADLAMP R/L	O/S CRACKED	1,962.40	981.20
2	FRONT HEADLAMP SIDE BRACKET R/L	NOT NECESSARY	97.70	-
1	FRONT GRILLE	CRACKED	574.10	574.10
1	FRONT GRILLE EMBLEM LOGO	NECESSARY	84.60	84.60
1	FRONT GRILLE UPPER FRAME BRACKET	CRACKED	42.20	42.20
1	FRONT BUMPER	DISTORTED	683.65	683.65
2	FRONT BUMPER SIDE RETAINER R/L	O/S DAMAGED	36.00	18.00
1	FRONT BUMPER FOGLAMP RH	CRACKED	326.65	326.65
1	FRONT BUMPER FOGLAMP COVER RH	CUT	102.72	102.72
1	FRONT FENDER RH	DENTED	336.00	336.00
1	FRONT FENDER ARCH GARNISH RH	CUT	216.60	216.60
2	FRONT FENDER INNER SHIELD R/L	TORN	259.20	259.20
1	AIR CLEANER BOX	NOT NECESSARY	144.10	-
	LESS 20% DISCOUNT		-1,348.96	-960.32
			5,395.86	3,841.30
1	FRONT SPORT RIM RH (SN)	CUT	1,020.00	580.00
	LESS 20% DISCOUNT		-204.00	-
			816.00	580.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT TYRE RH (SN)	CUT	350.00	180.00
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	40.00	20.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00

Report Ref No. CS/UOI23004548/Acy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SETS FRONT FENDER INNER SHIELD CLIP R/L (SN)	NECESSARY	100.00	60.00
			540.00	290.00
	LABOUR			
	TO REMOVE & REFIX ACCIDENT DAMAGED PARTS & REALIGN ACCIDENT AFFECTED AREA.		1,000.00	600.00
	TO SPRAY PAINT ACCIDENT AFFECTED AREA.		1,200.00	500.00
	TO REMOVE & REFIX FRONT UNDER CARRIAGE SUSPENSION.		250.00	200.00
	TO COMPUTERISE WHEEL ALIGNMENT.		120.00	80.00
	TO CHECK WIRING & HEADLAMP FOCUS.		50.00	30.00
	TO RUST PROOF ACCIDENT AFFECTED AREAS.	100.00	40.00	
			2,720.00	1,450.00
GRAND TOTAL			9,471.86	6,161.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,900.00

Report Ref No. CS/UOI23004548/Acy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.