

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/LPC 23004557/U93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: FRF 7499Tat Workshop m/s ERZAT Lee

of _____

Insured: XD924QJ

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: 85500

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 43364336
47483263Veh No: FRF 7499TYr Regn: 14/1/11Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha 7135 c.c. 135Colour: multi colourA/C: Insured / Std / NI / NASp. Reading: 68424T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 5YP303.459Gen. Cond: Good / Fair / Poor / BurntSteering: Insured / Jammed / Leaked / Burnt orBrake: Insured / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 70-90-17R: 70-90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or maxxis

Front

Rear

R/Bal. 6 mmR/Bal. 6 mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 28/04/23D.O.I. 4/5/23

Survey held at _____

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orN/S Frnt, O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

in number 0715767052counted 13-11-2026 so 3 yrs 6 mths.NOTE @ 22374/5 @ 2100 informed AH Lion

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1) _____

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 4-May-23

Estimate no.

1258

Plate No. FBF7499T

Model. YAMAHA SPARK 135

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET <i>3rd</i>	\$ 350.00	<i>3</i>	
2	FORK T-UNDER BRACKET <i>3rd</i>	\$ <i>160</i> 200.00	<i>3</i>	
3	STEERING CONE <i>new</i>	\$ 80 150.00	<i>2</i>	
4	FRONT SPORT RIM <i>new</i>	\$ 180.00	<i>✓</i>	
5	FRONT DISC BRAKE <i>new</i>	\$ 120.00	<i>x</i>	
6	FRONT FENDER <i>3rd</i>	\$ 98 120.00	<i>✓</i>	
7	HANDLE BAR <i>3rd</i>	\$ 180 250.00	<i>✓</i>	
8	HANDLE BRACKET <i>3rd</i>	\$ 90 120.00	<i>2</i>	
9	HANDLE BALANCER <i>new</i>	\$ 30 100.00	<i>✓</i>	
10	HANDLE COVER 1 <i>new</i>	\$ 75 100.00	<i>✓</i>	
11	HANDLE COVER 2 <i>new</i>	\$ 80.00	<i>x</i>	
12	MIRROR SET <i>3rd</i>	\$ 80 100.00	<i>✓</i>	
13	FRONT NUMBER PLATE <i>new</i>	\$ 20.00	<i>10</i>	
14	IU UNIT <i>new</i>	\$ 155.80	<i>✓</i>	
15	BRAKE LEVER <i>new</i>	\$ 68 80.00	<i>✓</i>	
16	CLUTH LEVER <i>3rd</i>	\$ 68 80.00	<i>✓</i>	
17	HEAD LAMP <i>new</i>	\$ 180.00	<i>✓</i>	
18	HEAD LAMP STAY <i>new</i>	\$ 150.00	<i>x</i>	
19	HEAD COVER <i>new</i>	\$ 175 200.00	<i>✓</i>	
20	FRONT TYRES SHAFT <i>new</i>	\$ 50 100.00	<i>2</i>	
21	FRONT FAIRING COVER RIGHT <i>new</i>	\$ 120.00	<i>✓</i>	
22	FRONT FAIRING COVER LEFT <i>new</i>	\$ 120.00	<i>✓</i>	
23	BRAKE PEDAL <i>3rd</i>	\$ 112 150.00	<i>✓</i>	
24	FRONT FOOTREST BAR <i>3rd</i>	\$ 115 200.00	<i>✓</i>	
25	FRONT FOOTREST RUBBER <i>new</i>	\$ 50.00	<i>✓</i>	

(10%)

*not Authorized
new
merch
90296608
4/5/23*

*2/5 \$ 2100
3 days.
Take photo After repair*

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 4-May-23

Estimate no. 1258

Plate No. FBF7499T

Model. YAMAHA SPARK 135

Surveyor's columns

S/N	DESCRIPTION (s)	R	PRICE (\$)	REMARK	PRICE (\$)
26	EXHAUST PIPE YOSHIMURA	<i>any</i>	\$ 900.00	<i>X</i>	
27	EXHAUST BRACKET	<i>any</i>	\$ 100 200.00	<i>✓</i>	
28	REAR FAIRING COVER RIGHT	<i>n</i>	\$ 200.00	<i>X</i>	
29	REAR BOX BRACKET	<i>any</i>	\$ 150 250.00	<i>✓</i>	
30	LABOUR		\$ 500.00	<i>250</i>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Less 10% \$ 552.58
 \$ 5,525.80
 Sub Total : \$ 4,973.22
 GST 8% \$ 397.86
 Total: \$ 5,371.08

2-2641
102
2376.9
250
2626.9
250
2876.9

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.