

REPAIR ESTIMATE\*

VEHICLE NO SH9642X

DATE 29.03.2023

MAKE REG.02.07.2019

MODEL : HYU IONIQ G2

CHIANG/CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET LH ? XNW			\$55.80
1	FRONT BUMPER SCR /			\$481.10
1	FRONT BUMPER CENTRE UPPER MOULDING XNW			\$368.50
1	FRONT BUMPER GRILLE LH / CFA /		\$186.50	\$186.50
1	FRONT DAY LIGHT RUNNING LH SCR /		\$642.50	\$642.50
1	FRONT FENDER LH XNW			\$588.80
1	FRONT FENDR SHIELD LH XNW			\$164.70
1	HEAD LAMP LH SCR & /			\$2,110.30
1	FRONT WHEEL COVER LH SCR -			\$346.40
	<b>SUB TOTAL</b>		3766.80	\$4,944.60
	<b>20.00%</b>		753.36	\$988.92
	<b>DISCOUNTED TOTAL</b>		3013.44	\$3,955.68
1	FENDER ADVERTISEMENT LH XNW			\$100.00
				\$100.00
	<b>Labour Charge</b>			
	Panel Beating		380	\$750.00
	Spray Paint		250	\$600.00
	Reset Front Wheel Alignment		XNW	\$60.00
	Check lighting		30	\$60.00
	<b>TOTAL LABOUR</b>			\$1,470.00
	<b>ESTIMATE TOTAL</b>		3673.44	\$5,525.68
			Wb = 734.68	
			= 2938.75	
			~ 2950	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3 days

L/S

29/3/23

4pm  
/ NW

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.