

HD PERFECT AUTOWORK PTE LTD

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 26.04.2023

ZGE200030437

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SJV196J**
MODEL : **TOYOTA WISH**
DATE OF ACCIDENT : 24.04.2023
TIME OF ACCIDENT : 17:30 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Distorted</i>	1	\$ 1,290.00	\$ 1,290.00
2	TAILGATE DAMPER <i>Neu</i>	2	\$ 229.60	\$ 459.20
3	TAILGATE STOPPER <i>Neu</i>	2	\$ 28.00	\$ 56.00
4	TAILGATE LOGO <i>Neu</i>	1	\$ 65.00	\$ 65.00
5	TAILGATE LAMP <i>LH cracked, RH ut</i>	2	\$ 298.00	\$ 596.00
6	TAILGATE OUTER MOULDING (CHROME) <i>Cracked</i>	1	\$ 290.00	\$ 290.00
7	TAILGATE INNER LOCK <i>R & C</i>	1	\$ 398.00	\$ 398.00
8	TAILGATE LOCK CATCH <i>Neu</i>	1	\$ 35.00	\$ 35.00
9	TAILGATE WEATHER STRIP <i>Cut</i>	1	\$ 320.00	\$ 320.00
10	TAILGATE INNER HOLDER <i>Rehnd</i>	1	\$ 118.10	\$ 118.10
11	TAILGATE INNER BOARD <i>Cracked</i>	1	\$ 450.00	\$ 450.00
12	TAILGATE WINDSCREEN MOULDING <i>Neu</i>	1	\$ 140.00	\$ 140.00
13	TAILGATE NUMBER PLATE LAMP <i>Neu</i>	2	\$ 68.00	\$ 136.00
14	REAR BUMPER <i>Rehnd</i>	1	\$ 694.30	\$ 694.30
15	REAR BUMPER REFLECTOR <i>Neu</i>	2	\$ 68.00	\$ 136.00
16	REAR BUMPER BRACKET <i>Distorted</i>	2	\$ 95.20	\$ 190.40
17	REAR BUMPER SIDE RETAINER <i>R & C</i>	2	\$ 60.00	\$ 120.00
18	REAR BUMPER CORNER RETAINER <i>Neu</i>	2	\$ 65.10	\$ 130.20
19	TAILLAMP <i>Cracked</i>	2	\$ 520.00	\$ 1,040.00

840.

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJV196J**
 MODEL : **TOYOTA WISH**
 DATE OF ACCIDENT : **24.04.2023**
 TIME OF ACCIDENT : **17:30 HOURS**

20	REAR FENDER LH <i>Buckled</i>	1	\$	940.00	\$	940.00	✓
21	REAR FENDER INNER COWLING <i>new</i>	2	\$	380.00	\$	760.00	+
22	REAR FENDER INNER TRIM <i>lit cnc-61</i>	2	\$	738.10	\$	1,476.20	738.10
23	REAR FENDER GLASS WITH MOULDING LH <i>new</i>	1	\$	560.00	\$	560.00	85
24	REAR FENDER AIR VENT LH <i>new</i>	1	\$	85.90	\$	85.90	+
25	REAR END PANEL <i>Dented</i>	1	\$	530.00	\$	530.00	-
26	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$	245.00	\$	245.00	-
27	REAR END PANEL BOTTOM (CENTRE) <i>new</i>	1	\$	420.00	\$	420.00	+
28	REAR FLOOR PANEL <i>Repair</i>	1	\$	975.40	\$	975.40	+
29	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$	425.00	\$	425.00	-
30	REAR FLOOR PANEL SIDE BOARD <i>new</i>	2	\$	125.00	\$	250.00	+
31	REAR FLOOR TOP BOARD INNER SUPPORT <i>new</i>	1	\$	596.80	\$	596.80	+
32	REAR SPARE TYRE CHAIN <i>new</i>	1	\$	330.00	\$	330.00	+
33	REVERSE SENSOR (SET) <i>Fixed</i>	1	\$	550.00	\$	550.00	200

8597.40
 6448.05

TOTAL PRICE \$ 14,808.50
 LESS 25% \$ 3,702.13
SUB TOTAL PRICE \$ 11,106.38

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Delud</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	TAILGATE INNER TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
4	TAILGATE INNER SIDE GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
5	TAILGATE EMBLEM 'VALVE MATIC' (SPECIAL TYPE) <i>new</i>	1	\$ 120.00	\$ 120.00
6	TAILGATE EMBLEM 'LION HEAD' <i>new</i>	1	\$ 60.00	\$ 60.00
7	TAILGATE WINDSCREEN SEALANT <i>2 new</i>	1	\$ 80.00	\$ 80.00
8	TAILGATE WINDSCREEN INNER SHIELD	1	\$ 60.00	\$ 60.00
9	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
10	REAR FENDER SEALANT <i>Not in</i>	1	\$ 120.00	\$ 120.00
11	REAR FENDER GLASS INNER SHIELD <i>new</i>	1	\$ 60.00	\$ 60.00
12	REAR FENDER GLASS SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
13	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00
14	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJV196J**
 MODEL : **TOYOTA WISH**
 DATE OF ACCIDENT : **24.04.2023**
 TIME OF ACCIDENT : **17:30 HOURS**

15	REAR SPARE TYRE (SPECIAL TYPE) <i>AK m</i>	1	\$ 350.00	\$ 350.00	<i>x</i>
16	REVERSE CAMERA <i>Not Nec</i>	1	\$ 480.00	\$ 480.00	<i>x</i>

380

TOTAL \$ 1,910.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	<i>200 1200</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	<i>1000</i>
3	TUFF COAT	\$ 450.00	<i>60</i>
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>60</i>
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	TRANSFER TAILGATE MECHANISM	\$ 80.00	<i>60</i>
8	CONDUCT WATER LEAKAGE TEST	\$ 250.00	<i>x</i>
9	REMOVE AND REFIX REAR FENDER GLASS	\$ 100.00	<i>40</i>
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>
11	REMOVE AND REFIX VIDEO CAMERA	\$ 80.00	<i>50</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJV196J**
 MODEL : **TOYOTA WISH**
 DATE OF ACCIDENT : **24.04.2023**
 TIME OF ACCIDENT : **17:30 HOURS**

12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	X.
----	--	-----------	----

TOTAL \$ 5,340.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 13,016.38
 TOTAL LABOUR COST : \$ 5,340.00
 TOTAL REPAIR COST : \$ 18,356.38

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

Adrian Lj
2/s 26/04/23.
00 Days.

Total: 9458.05
2/s: 7.61c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: