



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7958E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	CRACKED	459.40	459.40
1	REAR BUMPER SIDE BRACKET RH	NOT NECESSARY	55.80	-
1	REAR BUMPER CENTRE MOULDING	SCRATCHED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
1	REAR BUMPER REINFORCEMENT STAY LH	NOT NECESSARY	138.10	-
1	REAR BUMPER REFLECTOR RH	SCRATCHED	41.45	41.45
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-312.56	-194.82
			1,250.24	779.28
	<b><u>NETT ITEMS</u></b>			
1	REAR REVERSE SENSOR (N)	NOT NECESSARY	180.00	-
	LESS 10% DISCOUNT		-18.00	-
			162.00	-
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		600.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK LIGHTING / WIRING.		60.00	30.00
	REMOVE / REFIX REVERSE SENSOR.		60.00	30.00
			1,020.00	660.00
	<b>GRAND TOTAL</b>		<b>2,432.24</b>	<b>1,439.28</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,150.00</b>

Report Ref No. NS/INC23004627/Svp3e2

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.