



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. SGU 4268A

Qty	Description of Parts	Condition	Recommended (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>		
1	REAR BUMPER	BUCKLED	708.00
1	REAR BUMPER CLIPS	NECESSARY	30.00
1	REAR END PANEL	DAMAGED	482.00
1	REAR LH TAILLAMP }	SCRATCHED	670.00
1	REAR RH TAILLAMP }	CRACKED	-
1	TAILGATE	DENTED	828.40
1	TAILGATE EMBLEM	NECESSARY	53.00
1	TAILGATE MOULDING	NECESSARY	230.00
1	REAR LH FENDER	TO REPAIR SEE LABOUR	-
1	REAR RH FENDER	TO REPAIR SEE LABOUR	-
1	TAILGATE C AND C EMBLEM	NECESSARY	85.00
1	TAILGATE MIVEC	NECESSARY	43.00
1	TAILGATE ATTRAGE	NECESSARY	21.00
	LESS 10% DISCOUNT		-315.04
			2,835.36
	<b><u>LABOUR</u></b>		
	PANEL. INCLUSIVE OF THE REPAIR OF REAR LH FENDER AND REAR RH FENDER.		1,000.00
	RESPRAY.		800.00
			1,800.00
<b>GRAND TOTAL</b>			<b>4,635.36</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>	<b>3,700.00</b>
---	-----------------

Report Ref No. CS3/SPF23004642/Wvy3e2

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$3,700-\$5,000**

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.