



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

OPINION ON REPAIR COST FOR VEHICLE NO. SKS 6962D

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	REAR BUMPER	DEFORMED	1,105.20
1	REAR BUMPER SIDE RETAINER	DEFORMED	72.30
1	REAR BUMPER LOWER GARNISH	DEFORMED	678.20
1	REAR BUMPER REINFORCEMENT	* CHECK	-
1	REAR BUMPER SPONGE	* CHECK	-
1	BOOTLID	BENT	1,200.00
1	BOOTLID LAMP LH	CRACKED	554.00
1	BOOTLID LAMP RH	* CHECK	-
1	BOOTLID CHROME MOULDING	DEFORMED	220.00
1	BOOTLID EMBLEM LOGO	NECESSARY	65.00
1	BOOTLID EMBLEM 'LEXUS'	NECESSARY	68.00
1	BOOTLID EMBLEM 'GS250'	NECESSARY	60.00
1	BOOTLID LOCK	* CHECK	-
1	TAILLAMP LH	CRACKED	1,039.00
1	TAILLAMP RH	* CHECK	-
1	REAR END PANEL	* CHECK	-
1	REAR END PANEL GARNISH	* CHECK	-
1	REAR LH FENDER	TO REPAIR SEE LABOUR	-
1	FRT BUMPER NUMBER PLATE GARNISH	DEFORMED	60.00
1	FRT BUMPER	DEFORMED	1,163.00
1	FRT GRILLE	CRACKED	596.00
1	FRT GRILLE CHROME MOULDING	CRACKED	407.00
1	FRT GRILLE EMBLEM	CUT	174.00
1	FRT BUMPER LOWER GRILLE	DEFORMED	220.00
1	FRT BUMPER REINFORCEMENT	* CHECK	-
1	FRT BUMPER SPONGE	* CHECK	-
1	FRT HEADLAMP	* CHECK	-
	LESS 10% DISCOUNT		-768.17
			6,913.53
	<u>SPECIAL NETT ITEMS</u>		
1	REAR BUMPER CLIPS (SN)	NECESSARY	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	250.00

Report Ref No. CS3/SPF23004645/Tny3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Recommended (\$)
1	REAR NUMBER PLATE (SN)	BENT	45.00
1	FRT NUMBER PLATE (SN)	BENT	45.00
			370.00
	LABOUR		
	TO REPAIR FRONT & REAR PORTION. INCLUSIVE OF THE REPAIR OF REAR LH FENDER.		1,600.00
	TO RESPRAY FRONT & REAR PORTION.		1,600.00
	WIRING FRONT & REAR PORTION.		60.00
	TUFF COAT.		80.00
	REMOVE & REFIX FRONT & REAR REVERSE SENSOR.		80.00
	REMOVE & REFIX REAR BOOTLID MECHANISM.		60.00
			3,480.00
GRAND TOTAL			10,763.53

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (EXCLUDE CHECK ITEMS S\$6,746.04 NETT)	8,600.00
--	-----------------

Report Ref No. CS3/SPF23004645/Tny3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$8,600-\$12,000

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.