



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

Ref: CS3/SPF23004645/Tny3e2

ACCIDENT CLAIMS SECTION(SPORE POLICE  
FORCE)POLICE LOGISTICS BASE (PLB)1  
HEMMANT ROAD SINGAPORE 438675

Date: 28/06/2023

ATTN: LUI LAI KUEN

Code: SPF

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 2034L	Veh. Inspected	SKS 6962D
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/030	Excess (\$)	0.00
Assign From	LUI LAI KUEN	Assign Date	06/05/2023

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA LEXUS GS250	c.c	2500
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTHBF5BL00A000908	Colour	GREY
Odometer	103724 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/50 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/50 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/50 R17	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	06/05/2023	Inspect Date / Time	08/05/2023 ( 12:30 PM )
Survey held at	175 ENG KONG GARDEN S599273		
Repairer	-		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------