

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23004652/UVP3Q2**Date:** 18/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00039332204
Claimant Vehicle No :	GBH6568Z	Insured Vehicle No :	YP2320H
Date of Loss:	12/02/2023	Nature of Claim: TP	Claim No: SNM23D201219/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH6568Z	Engine No:	1KD2812423
Make & Model:	TOYOTA DYNA 150, 2.8 D 5MT (M)	Chassis No:	JTFAT35Y90K211057
Reg. Date:	03/08/2018 (Man. Year: 2018)	Odometer:	112534 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	KAPSEN 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	KAPSEN 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,298.95	4,335.27	2,963.68	40.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,110.00	2,160.00	2,950.00	57.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,408.95	6,495.27	5,913.68	47.66
Approved Total (Overridden) (S\$)		5,100.00		
Nett Amount (S\$)	12,408.95	5,100.00	7,308.95	58.90

INSPECTION

Date of Assignment:	07/05/2023		
Date Inspected:	05/05/2023	Inspected At:	Sin Hwee Motor Pte Ltd (HQ) Blk 3023A, Ubi Road 1, #01-59 Singapore 408717
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 May 2023)	
Parts:	N/A	TOYOTA DYNA 150 2.8 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH6568Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WINDSCREEN RUBBER	Necessary	295.48 FL	*295.48 FL
2	1		*WIPER ARM CAP	Missing	38.77 FL	*38.77 FL
3	1		*WIPER PANEL	Bent	468.12 FL	*468.12 FL
4	1		*FRONT PANEL	Badly Dented	1,144.90 FL	*1,144.90 FL
5	1		*CENTER GRILLE	Cracked	581.79 FL	*581.79 FL
6	1		*R/H SIDE FENDER	Dented	358.97 FL	*358.97 FL
7	1		*SIDE MIRROR ASSY	Bent	606.48 FL	*606.48 FL
8	1		*DYNA LOGO	Serviceable	38.00 FL	*- FL
9	1		*CENTER LOGO	Necessary	98.05 FL	*98.05 FL
10	2		*FRONT HEADLAMP	Not Necessary	2,291.58 FL	*- FL
11	1		*WASHER TANK	Deformed	221.50 FL	*221.50 FL
12	1		*AIR CON UNIT	Cracked	1,920.10 FL	*1,920.10 FL
13	1		*PANEL INNER BRACKET	Bent	46.20 FL	*46.20 FL
						F=Franchise part. L=ListItemDisc.
Sub Total (\$\$)					8,109.94	5,780.36
- List Item Discount on L Items 10.00/25.00% (\$\$)					810.99	1,445.09
Total Parts (\$\$)					7,298.95	4,335.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMOUNT AND MOUNT FRONT WINDSCREEN TO FACILITATE REPAIR WORK	New	200.00	80.00
2	TO DISMOUNT AND MOUNT DASHBOARD TO FACILITATE REPAIR WORK	New	550.00	200.00
3	TO RESTORE FRONT PANEL AND WIPER PANEL INCLUDE KNOCKING AND WELDING TO ALIGN FRONT R/H DOOR INCLUDE JACKING AND PULLING TO REPLACE AND INSTALL ABOVE ITEMS	New	2,200.00	900.00
4	TO SPRAY PAINT FRONT PANEL ,WIPER PANEL ,SIDE FENDER ,GRILLE AND BUMPER	New	1,500.00	800.00
5	TO CARPET OUT WIRE CHECKING AND TESTING	New	80.00	20.00
6	TO SUPPLY AND TUFF KOTE	New	80.00	60.00
7	TO REMOVE AND REFIX AIR CON SYSTEM TO FACILITATE REPAIR WORK TO SUPPLY AND TOP UP AIR CON GAS	New	250.00	100.00
8	TO REPLACE AND INSTALL ABOVE ITEMS TO SUPPLY AND TOP UP AIR CON GAS	New	250.00	0.00
Gross Labour Cost (\$\$)			5,110.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >