



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNG 5595P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BP-SUNDRY (SN)	NECESSARY	100.00	50.00
1	BACK SENSOR 218 ATTITUDE BLACK (SN)	NOT WORKING	101.05	101.05
1	COVER, RR BUMPER (SN)	DEFORMED	702.60	702.60
10	PIECE, RR BUMPER @\$5.10 (SN)	NECESSARY	51.00	51.00
1	SPOILER, RR NO.1 (SN)	CUT	1,069.20	1,069.20
1	SUPPORT, RR BUMPER (SN)	NOT NECESSARY	179.80	-
1	RETAINER, RR BUMPER (SN)	NECESSARY	74.30	74.30
1	SUPPORT, RR BUMPER (SN)	NOT NECESSARY	179.80	-
1	RETAINER, RR BUMPER (SN)	NECESSARY	74.30	74.30
1	REINFORCEMENT (SN)	NOT NECESSARY	273.70	-
1	ARM SUB-ASSY, RR (SN)	NOT NECESSARY	221.30	-
1	ARM SUB-ASSY, RR (SN)	NOT NECESSARY	221.30	-
			3,248.35	2,122.45
	<u>LABOUR</u>			
	DRILL HOLE AND INSTALL REVERSE SENSOR.		198.00	198.00
	CHECK WIRING SYSTEM.		134.64	134.64
	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR.	NOT NECESSARY	396.00	-
	TO RESET ECU AND REPROGRAMME.		198.00	198.00
	REPLACE ACC DAMAGED PARTS.		2,376.00	792.00
	RESPRAY ACC AFFECTED AREAS.		1,968.00	656.00
			5,270.64	1,978.64
	GRAND TOTAL		8,518.99	4,101.09
	RECOMMENDED COST OF REPAIRS			4,101.09

Report Ref No. CS/SMR23004659/Rqy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.