

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG23004665/KNY3M4**Date:** 12/05/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001874833
<b>Claimant Vehicle No :</b>	SLT851M	<b>Insured Vehicle No :</b>	FBG7182B
Date of Loss:	04/05/2023	Nature of Claim:	TP
		Claim No:	313441

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLT851M</b>	Engine No:	2ZR8197700
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Chassis No:	ZYX102076275
Reg. Date:	17/10/2017 (Man. Year: 2017)	Odometer:	613051 km
Colour:	Metallic Yellow		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,020.65	2,332.32	1,688.33	41.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	900.00	840.00	48.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,760.65</b>	<b>3,232.32</b>	<b>2,528.33</b>	<b>43.89</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,760.65</b>	<b>2,600.00</b>	<b>3,160.65</b>	<b>54.87</b>

INSPECTION

Date of Assignment:	10/05/2023	
Date Inspected:	09/05/2023	Inspected At: LIAN HER MOTORS BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541.
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2023)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT851M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR O/S TAIL-GATE REFLECTOR	Cut	550.10 FL	*472.20 FL
2	1		*REAR TAIL-GATE OUTER GARNISH	Mtg Cracked	875.10 FL	*875.10 FL
3	1		*REAR BUMPER	Buckled	785.60 FL	*545.10 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	483.20 FL	*455.10 FL
5	1		*REAR O/S BUMPER REFLECTOR GARNISH	Serviceable	125.60 FL	*- FL
6	1		*REAR O/S BUMPER REFLECTOR	Serviceable	95.70 FL	*- FL
7	1		*REAR LOWER BUMPER	Cracked	455.60 FL	*455.60 FL
8	1		*REAR TOW COVER	Serviceable	55.10 FL	*- FL
9	2		*REAR BUMPER SIDE RETAINER	Serviceable	150.20 FL	*- FL
10	2		*REAR FENDER ARCH GARNISH	Serviceable	350.20 FL	*- FL
11	1		*REAR END PANEL	Repair	725.70 FL	*- FL
12	1		*REAR END PANEL INNER GARNISH	Serviceable	402.10 FL	*- FL
13	15		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
14	1		*REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,284.20	3,033.10
- List Item Discount on L Items 25.00/25.00% (S\$)	1,263.55	700.78
Total Parts (S\$)	4,020.65	2,332.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING	New	800.00	400.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	800.00	480.00
3	CHECK AND RECONNECT WIRING	New	40.00	20.00
4	TO ANTI-RUST PROOFING	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,740.00</b>	<b>900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >