



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 228R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT GRILLE	NOT NECESSARY	1,607.10	-
1	FRONT GRILLE - BLACK	CUT	438.20	438.20
1	FRONT NUMBER PLATE GARNISH	NOT NECESSARY	43.50	-
2	FRONT BUMPER SENSOR @\$183.60	NOT NECESSARY	367.20	-
	LESS 20% DISCOUNT		-491.20	-87.64
			1,964.80	350.56
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE W CASING (SN)	CUT	60.00	30.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
			90.00	60.00
	<u>LABOUR</u>			
	TO PANEL BEAT / STRAIGHTEN / REALIGN ACCIDENT AFFECTED AREAS.		800.00	250.00
	TO SPRAY PAINT ON AFFECTED AREAS.		800.00	150.00
	TO CHECK AND REALIGN HEADLAMP AND FOCUS.	NOT NECESSARY	60.00	-
			1,660.00	400.00
GRAND TOTAL			3,714.80	810.56
RECOMMENDED COST OF REPAIRS				810.56

Report Ref No. CS/AGI23004666/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.