

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG23004696/AYA3Q2**Date:** 20/07/2023**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 7210059580   |
| <b>Claimant Vehicle No :</b> | SLW4176L                             | <b>Insured Vehicle No :</b> | SNA5711C     |
| Date of Loss:                | 06/05/2023                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 4834179868SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |              |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No:                     | <b>SLW4176L</b>                   | Engine No:  | 2ZR8233674   |
| Make & Model:               | TOYOTA C-HR HYBRID, 1.8 S (A)     | Chassis No: | ZYX102084816 |
| Reg. Date:                  | 09/02/2018 (Man. Year: 2017)      | Odometer:   | 101410 km    |
| Colour:                     | Yellow                            |             |              |
| Engine Capacity:            | 1797 cc                           |             |              |
| Market Value/New Car Price: | N/A                               |             |              |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |              |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 215/60 R17 | Rear Tyre Size:  | 215/60 R17 |
| Front Left Side:  | Giti 6 mm  | Rear Left Side:  | Giti 6 mm  |
| Front Right Side: | Giti 6 mm  | Rear Right Side: | Giti 6 mm  |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 28,225.82         | 20,259.47         | 7,966.35          | 28.22         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 8,640.00          | 4,280.00          | 4,360.00          | 50.46         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>36,865.82</b>  | <b>24,539.47</b>  | <b>12,326.35</b>  | <b>33.44</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>19,600.00</b>  |                   |               |
| <b>Nett Amount (S\$)</b>                 | <b>36,865.82</b>  | <b>19,600.00</b>  | <b>17,265.82</b>  | <b>46.83</b>  |
| <b>Global Sum Settlement (S\$)</b>       |                   | <b>0.00</b>       |                   |               |

**INSPECTION**

|                             |                          |                                       |
|-----------------------------|--------------------------|---------------------------------------|
| Date of Assignment:         | 08/05/2023               | MG Solution Pte Ltd (HQ)              |
| Date Inspected:             | 08/05/2023 Inspected At: | 23 Kaki Bukit Avenue 4 #02-03B, VICOM |
|                             |                          | Inspection Centre                     |
|                             |                          | Singapore 415933                      |
| Estimated Period of Repair: | 13.0 days                |                                       |

**Adjuster:** ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                              | Condition     | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT BONNET                            | Dented        | 820.50 FL   | *820.50 FL   |
| 2   | 1   |          | *FRONT BONNET LOCK                       | Damaged       | 180.00 FL   | *180.00 FL   |
| 3   | 1   |          | *FRONT BONNET BRACE PANEL                | Bent          | 192.50 FL   | *192.50 FL   |
| 4   | 1   |          | *FRONT BUMPER                            | Deformed      | 680.00 FL   | *680.00 FL   |
| 5   | 1   |          | *FRONT BUMPER LOWER LID                  | Deformed      | 522.60 FL   | *522.60 FL   |
| 6   | 2   |          | *FRONT BUMPER SIDE RETAINER              | Damaged       | 124.80 FL   | *124.80 FL   |
| 7   | 1   |          | *FRONT BUMPER TOWING COVER               | Not Necessary | 80.00 FL    | *- FL        |
| 8   | 2   |          | *FRONT BUMPER OUTER GARNISH              | Not Necessary | 244.60 FL   | *- FL        |
| 9   | 1   |          | *FRONT BUMPER NUMBER PLATE HOLDER        | Deformed      | 130.00 FL   | *130.00 FL   |
| 10  | 2   |          | *FRONT BUMPER FOGLAMP                    | Not Necessary | 511.20 FL   | *- FL        |
| 11  | 1   |          | *FRONT BUMPER REINFORCEMENT              | Dented        | 420.00 FL   | *420.00 FL   |
| 12  | 2   |          | *FRONT BUMPER REINFORCEMENT BRACKET      | Not Necessary | 180.00 FL   | *- FL        |
| 13  | 1   |          | *FRONT BUMPER REINFORCEMENT SPONGE       | Cracked       | 144.20 FL   | *144.20 FL   |
| 14  | 1   |          | *FRONT BUMPER REINFORCEMENT BELOW        | Not Necessary | 233.50 FL   | *- FL        |
| 15  | 1   |          | *FRONT BUMPER REINFORCEMENT BELOW SPONGE | Not Necessary | 105.30 FL   | *- FL        |
| 16  | 1   |          | *FRONT CENTRE GRILLE (OUTER)             | Cracked       | 420.00 FL   | *420.00 FL   |
| 17  | 1   |          | *FRONT CENTRE GRILLE (INNER)             | Cracked       | 280.00 FL   | *280.00 FL   |
| 18  | 1   |          | *FRONT UPPER RUBBER                      | Not Necessary | 90.00 FL    | *- FL        |
| 19  | 1   |          | *FRONT LOGO                              | Cracked       | 955.30 FL   | *535.00 FL   |
| 20  | 1   |          | *FRONT LOGO RADAR                        | Cracked       | 1,355.80 FL | *1,355.80 FL |
| 21  | 2   |          | *HEADLAMP                                | Cracked       | 4,311.20 FL | *4,311.20 FL |
| 22  | 2   |          | *FRONT FENDER                            | Not Necessary | 576.60 FL   | *- FL        |
| 23  | 2   |          | *FRONT FENDER EMBLEM HYBRID              | Not Necessary | 180.00 FL   | *- FL        |
| 24  | 2   |          | *FRONT FENDER WHEEL ARCH                 | Not Necessary | 360.00 FL   | *- FL        |
| 25  | 2   |          | *FRONT SUPPORT PANEL                     | Bent          | 1,640.00 FL | *780.00 FL   |
| 26  | 1   |          | *FRONT SUPPORT PANEL TOP COVER           | Deformed      | 210.50 FL   | *210.50 FL   |
| 27  | 2   |          | *HORN                                    | Not Necessary | 220.00 FL   | *- FL        |
| 28  | 1   |          | *AIRCON CONDENSOR                        | Dented        | 1,168.20 FL | *1,168.20 FL |
| 29  | 2   |          | *AIRCON CONDENSOR SIDE GUIDE             | Not Necessary | 240.00 FL   | *- FL        |
| 30  | 1   |          | *RADIATOR                                | Not Necessary | 1,355.20 FL | *- FL        |
| 31  | 1   |          | *TAILGATE                                | Distorted     | 1,422.30 FL | *1,112.00 FL |
| 32  | 1   |          | *TAILGATE OUTER GARNISH                  | Cracked       | 1,055.30 FL | *882.00 FL   |
| 33  | 2   |          | *TAILGATE EMBLEM LOGO                    | Necessary     | 160.00 FL   | *160.00 FL   |
| 34  | 2   |          | *TAILGATE EMBLEM C-HR                    | Necessary     | 150.00 FL   | *150.00 FL   |
| 35  | 1   |          | *TAILGATE HYBRID EMBLEM                  | Necessary     | 95.20 FL    | *95.20 FL    |
| 36  | 2   |          | *TAILGATE HINGE                          | Not Necessary | 181.00 FL   | *- FL        |
| 37  | 2   |          | *TAILGATE DAMPER                         | Not Necessary | 311.20 FL   | *- FL        |
| 38  | 1   |          | *TAILGATE LOCK                           | Damaged       | 320.50 FL   | *320.50 FL   |
| 39  | 1   |          | *TAILGATE INNER BOARD                    | Cracked       | 520.80 FL   | *520.80 FL   |
| 40  | 1   |          | *TAILGATE INNER HANDLE                   | Deformed      | 90.00 FL    | *90.00 FL    |
| 41  | 1   |          | *TAILGATE WEATHERSTRIP                   | Cut           | 255.20 FL   | *255.20 FL   |
| 42  | 1   |          | *TAILGATE DETECTOR                       | Cracked       | 180.20 FL   | *180.20 FL   |
| 43  | 2   |          | *TAILGATE LAMP                           | Cracked       | 911.60 FL   | *911.60 FL   |
| 44  | 1   |          | *TAILGATE WINDSCREEN SIDE GARNISH LH     | Missing       | 90.00 FL    | *90.00 FL    |
| 45  | 1   |          | *TAILGATE WINDSCREEN MOULDING            | Necessary     | 211.50 FL   | *211.50 FL   |
| 46  | 1   |          | *REAR BUMPER TOP                         | Deformed      | 850.00 FL   | *850.00 FL   |
| 47  | 1   |          | *REAR BUMPER LOWER                       | Deformed      | 580.00 FL   | *580.00 FL   |
| 48  | 2   |          | *REAR BUMPER SIDE RETAINER               | Damaged       | 124.80 FL   | *124.80 FL   |
| 49  | 2   |          | *REAR BUMPER REFLECTOR                   | Not Necessary | 181.00 FL   | *- FL        |
| 50  | 2   |          | *REAR BUMPER REFLECTOR HOUSING           | Cracked       | 365.00 FL   | *365.00 FL   |
| 51  | 1   |          | *REAR BUMPER TOWING COVER                | Missing       | 80.00 FL    | *80.00 FL    |
| 52  | 1   |          | *REAR BUMPER BRAKE LIGHT COVER           | Cracked       | 105.30 FL   | *105.30 FL   |
| 53  | 1   |          | *REAR BUMPER REINFORCEMENT               | Dented        | 560.20 FL   | *560.20 FL   |
| 54  | 2   |          | *REAR BUMPER SCREW COVER                 | Not Necessary | 60.00 FL    | *- FL        |
| 55  | 2   |          | *TAILLAMP                                | Cracked       | 1,300.60 FL | *1,300.60 FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Amount     |
|-----|-----|----------|---------------------------------------|---------------|-------------|------------|
| 56  | 2   |          | *TAILLAMP PANEL                       | Repair        | 423.20 FL   | *- FL      |
| 57  | 2   |          | *REAR WHEEL ARCH                      | Cracked       | 467.00 FL   | *467.00 FL |
| 58  | 1   |          | *REAR FENDER INNER COWLING (REAR)     | N/S Torn      | 245.20 FL   | *122.60 FL |
| 59  | 2   |          | *REAR FENDER INNER TRIM               | Cracked       | 1,240.00 FL | *998.00 FL |
| 60  | 1   |          | *REAR END PANEL                       | Dented        | 860.20 FL   | *731.00 FL |
| 61  | 1   |          | *REAR END PANEL TOP GARNISH           | Deformed      | 189.30 FL   | *189.30 FL |
| 62  | 1   |          | *REAR FLOOR PANEL                     | Repair        | 1,055.20 FL | *- FL      |
| 63  | 1   |          | *REAR FLOOR PANEL TOP COVER           | Deformed      | 688.20 FL   | *591.00 FL |
| 64  | 1   |          | *REAR TOOL SPONGE                     | Deformed      | 455.60 FL   | *371.00 FL |
| 65  | 2   |          | *REAR TOOL SIDE SPONGE                | Deformed      | 511.20 FL   | *511.20 FL |
| 66  | 1   |          | *REAR EXHAUST PIPE                    | Dented        | 920.00 FL   | *920.00 FL |
| 67  | 2   |          | *REAR EXHAUST PIPE MOUNTING           | Not Necessary | 160.00 FL   | *- FL      |
| 68  | 1   |          | *REAR EXHAUST PIPE SHIELD HEAT        | Dented        | 288.30 FL   | *110.00 FL |
| 69  | 1   |          | *FRONT NUMBER PLATE                   | Cracked       | 50.00 FS    | *50.00 FS  |
| 70  | 1   |          | *SET FRONT BUMPER CLIPS               | Necessary     | 20.00 FS    | *20.00 FS  |
| 71  | 1   |          | *SET CENTRE GRILLE CLIPS              | Necessary     | 20.00 FS    | *20.00 FS  |
| 72  | 1   |          | *SET FRONT FENDER WHEEL ARCH CLIPS    | Not Necessary | 22.00 FS    | *- FS      |
| 73  | 1   |          | *RADIATOR COOLANT                     | Not Necessary | 100.00 FS   | *- FS      |
| 74  | 1   |          | *REAR NUMBER PLATE                    | Cracked       | 50.00 FS    | *50.00 FS  |
| 75  | 1   |          | *SET TAILGATE INNER BOARD CLIPS       | Necessary     | 20.00 FS    | *20.00 FS  |
| 76  | 1   |          | *TAILGATE WINDSCREEN SEALANT          | Necessary     | 120.00 FS   | *60.00 FS  |
| 77  | 1   |          | *SET REAR BUMPER CLIPS                | Necessary     | 20.00 FS    | *20.00 FS  |
| 78  | 1   |          | *SET REAR FENDER INNER TRIM CLIPS     | Necessary     | 22.00 FS    | *22.00 FS  |
| 79  | 1   |          | *SET REAR FENDER INNER COWLING CLIPS  | Necessary     | 20.00 FS    | *20.00 FS  |
| 80  | 1   |          | *SET REAR FENDER WHEEL ARCH CLIPS     | Necessary     | 22.00 FS    | *22.00 FS  |
| 81  | 1   |          | *REAR END PANEL SEALANT               | Necessary     | 150.00 FS   | *60.00 FS  |
| 82  | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS | Necessary     | 22.00 FS    | *22.00 FS  |
| 83  | 1   |          | *REAR FLOOR PANEL SEALANT             | Not Necessary | 150.00 FS   | *- FS      |
| 84  | 1   |          | *REVERSE CAMERA                       | Not Necessary | 500.00 FS   | *- FS      |
| 85  | 1   |          | *REVERSE SENSOR                       | Damaged       | 220.00 FS   | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                  |                  |
|----------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$)</b>                                    | <b>37,125.10</b> | <b>26,817.30</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$)</b> | 8,899.28         | 6,557.83         |
| <b>Total Parts (\$)</b>                                  | <b>28,225.82</b> | <b>20,259.47</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                            | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                        |          |                 |                 |
| 1                              | PANEL BEATING ,REMOVAL AND REPLACING PARTS             | New      | 1,400.00        | 600.00          |
| 2                              | TO SPRAY PAINT AFFECTED AREA                           | New      | 1,400.00        | 600.00          |
| 3                              | TUFF COAT                                              | New      | 250.00          | 40.00           |
| 4                              | WIRING CHECK                                           | New      | 100.00          | 30.00           |
| 5                              | TO REMOVE AND REFIX AIRCON CONDENSOR AND TOP UP GAS    | New      | 120.00          | 60.00           |
| 6                              | TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST | New      | 100.00          | 0.00            |
| 7                              | PANEL BEATING ,REMOVAL AND REPLACING PARTS             | New      | 2,000.00        | 1,000.00        |
| 8                              | TO SPRAY PAINT AFFECTED AREA                           | New      | 2,000.00        | 1,400.00        |
| 9                              | TUFF COAT                                              | New      | 250.00          | 80.00           |
| 10                             | WIRING CHECK                                           | New      | 100.00          | 30.00           |
| 11                             | UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR         | New      | 250.00          | 80.00           |
| 12                             | TO REMOVE AND REFIX TAILGATE MECHANISM                 | New      | 120.00          | 60.00           |
| 13                             | TO REMOVE AND REFIX TAILGATE WINDSCREEN                | New      | 140.00          | 120.00          |
| 14                             | TO REMOVE AND REFIX REVERSE SENSOR                     | New      | 80.00           | 50.00           |
| 15                             | TO REMOVE AND REFIX REVERSE CAMERA                     | New      | 80.00           | 50.00           |
| 16                             | TO REMOVE AND REFIX EXHAUST PIPE                       | New      | 250.00          | 80.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                        |          | <b>8,640.00</b> | <b>4,280.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >