

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**ECICS Limited  
10 Eunus Road 8, #09-04A Singapore Post Centre  
Singapore 408600**Our File No:** CS/ICS23004697/UQY3M4**Date:** 31/05/2023**REFERENCE**

Insured/Claimant:	AHMAD BIN KASSIM	Policy No:	MPC23A00067600		
Date of Loss:	07/05/2023	Nature of Claim:	OD	Claim No:	DMPC2300337H/CT

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKR7847C</b>	Engine No:	1ZRY138195
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH104523744
Reg. Date:	09/03/2015 (Man. Year: 2014)	Odometer:	81695 km
Colour:	Red		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$32,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 ZR16	Rear Tyre Size:	205/55 ZR16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,097.60	2,437.60	660.00	21.31
Miscellaneous Items	60.00	40.00	20.00	33.33
Labour	2,310.00	1,660.00	650.00	28.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,467.60</b>	<b>4,137.60</b>	<b>1,330.00</b>	<b>24.33</b>
<b>- Excess (S\$)</b>	0.00	1,100.00	-1,100.00	
<b>(S\$)</b>	5,467.60	3,037.60	2,430.00	44.44
<b>+ GST 8.00/8.00% (S\$)</b>	437.41	243.01	194.40	44.44
<b>Nett Amount (S\$)</b>	<b>5,905.01</b>	<b>3,280.61</b>	<b>2,624.40</b>	<b>44.44</b>

**INSPECTION**

Date of Assignment:	09/05/2023	Present Location:	SME Motor Pte Ltd (Kaki Bukit) SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883
Date Inspected:	09/05/2023	Inspected At:	
Estimated Period of Repair:	5.0 days		

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2023)
<b>Parts:</b> 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKR7847C)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH TAIL LAMP (WCP)	Broken	165.00 F	*165.00 F
2	1		*REAR LH BOOT LAMP (WCP)	Cracked	145.00 F	*145.00 F
3	1		*REAR BUMPER (WCP)	Cut	250.00 F	*250.00 F
4	1		*REAR BUMPER RETAINER LH (WCP)	Cracked	50.00 F	*50.00 F
5	10		*REAR BUMPER CLIP (WCP)	Necessary	20.00 F	*20.00 F
6	1		*REAR LH TAIL LAMP PANEL (WCP)	Repair	65.00 F	*- F
7	2		*REAR TAIL LAMP CLIP (WCP)	Not Necessary	10.00 F	*- F
8	1		*REAR LH FENDER (WCP)	Badly Dented	450.00 F	*450.00 F
9	1		*REAR WINDSCREEN MOULDING (WCP)	Necessary	65.00 F	*65.00 F
10	1		*REAR PETROL TANK COVER (WCP)	Distorted	80.00 F	*80.00 F
11	5		*REAR PETROL TANK COVER RIVERT (WCP)	Necessary	10.00 F	*10.00 F
12	1		*REAR PETROL TANK NECK NO STOCK (WCP)	Serviceable	450.00 F	*- F
13	1		*REAR PETROL TANK SCREW COVER NO STOCK (WCP)	Cracked	220.00 F	*220.00 F
14	1		*REAR LH DOOR (WCP)	Badly Dented	495.00 F	*495.00 F
15	1		*REAR LH DOOR TOP STICKER (WCP)	Necessary	40.00 F	*40.00 F
16	1		*REAR LH DOOR OUTER MOULDING (WCP)	Not Necessary	75.00 F	*- F
17	1		*REAR LH DOOR OUTER HANDLE (WCP)	Cut	85.00 F	*85.00 F
18	1		*REAR LH DOOR OUTER HANDLE KNOB (WCP)	Cut	25.00 F	*25.00 F
<b>Supplementary #1</b>						
19	2		*REAR LH DOOR HANDLE (WCP)	Torn	16.00 F	*16.00 F
20	1		*REAR PETROL TANK COVER RUBBER (WCP)	Torn	50.00 F	*50.00 F
21	1		*REAR PETROL TANK COVER CABLE (WCP)	Torn	50.00 F	*50.00 F

F=Franchise part.

<b>Sub Total (S\$)</b>	<b>2,816.00</b>	<b>2,216.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (S\$)</b>	281.60	221.60
<b>Total Parts (S\$)</b>	<b>3,097.60</b>	<b>2,437.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	REAR WINDSCREEN GUM (Necessary)	60.00	40.00
			<b>Sub Total (\$\$)</b>	<b>60.00</b>
				<b>40.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	REMOVE & REFIX CUSHION AND SEATS	New	180.00	60.00
4	REMOVE & REFIX PETROL TANK	New	180.00	60.00
5	LABOUR CHARGE	New	900.00	700.00
6	SPRAY PAINTING	New	900.00	700.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,310.00</b>
				<b>1,660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >