

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III23002988/SNP3E2-1**Date:** 31/05/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_02
Claimant Vehicle No : GBE9702Z **Insured Vehicle No :** SLQ8124S
 Date of Loss: 17/03/2023 Nature of Claim: TP Claim No: MFL2023D0003155

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE9702Z**
 Make & Model: TOYOTA HIACE, 3.0 (A) Engine No: 1KD2573426
 Reg. Date: 04/05/2016 (Man. Year: 2015) Chassis No: KDH2010184812
 Colour: Silver Odometer: 403492 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
 Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,130.43	3,314.33	3,816.10	53.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,390.00	1,700.00	1,690.00	49.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,520.43	5,014.33	5,506.10	52.34
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	10,520.43	4,000.00	6,520.43	61.98

INSPECTION

Date of Assignment: 09/05/2023
 Date Inspected: 23/03/2023 Inspected At: Prowerkz Garage Pte Ltd (HQ)
 25 Kaki Bukit Road 4, #06-87 Synergy @ KB
 Singapore 417800
 Estimated Period of Repair: 6.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 May 2023)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE9702Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Damaged	1,673.50 FL	*1,673.50 FL
2	2		*REAR TAILGATE DAMPERS	Not Necessary	590.00 FL	*- FL
3	1		*REAR TAILGATE INNER BOARD	Not Necessary	408.00 FL	*- FL
4	1		*REAR TAILGATE LOCK CATCH	Not Necessary	48.50 FL	*- FL
5	1		*REAR TAILGATE LOCK	Damaged	390.45 FL	*279.00 FL
6	1		*REAR TAILGATE LOGO	Necessary	61.90 FL	*61.90 FL
7	1		*REAR TAILGATE OUTER GARNISH	Damaged	124.10 FL	*124.10 FL
8	1		*REAR TAILGATE RUBBER	Damaged	328.48 FL	*328.48 FL
9	1		*REAR TAILLAMPS	O/S Damaged	493.00 FL	*246.50 FL
10	1		*REAR END PANEL	Damaged	887.90 FL	*596.00 FL
11	1		*REAR END PANEL TOP MOULDING	Damaged	99.20 FL	*99.20 FL
12	4		*REAR END PANEL LOWER BLACKETS	Damaged	328.40 FL	*120.00 FL
13	1		*REAR BUMPER	Damaged	517.10 FL	*517.10 FL
14	1		*REAR FLOOR PANEL	Repair	1,968.50 FL	*- FL
15	1		*REAR SPARE TYRE CARRIAGE	Repair	331.20 FL	*- FL
16	1		*REAR SPARE TYRE LOCK CATCH	Not Necessary	110.35 FL	*- FL
17	1		*REAR WINDSCREEN SEAL	Damaged	85.00 FS	*20.00 FS
18	1		*REAR WINDSCREEN SEALANT	Damaged	90.00 FS	*40.00 FS
19	1		*REAR TAILGATE 70KM/H STOCLE	Necessary	25.00 FS	*20.00 FS
20	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
21	1		*REAR FLOOR PANEL BOARD	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,220.58	4,325.78
- List Item Discount on L Items 25.00/25.00% (\$)	2,090.15	1,011.45
Total Parts (\$)	7,130.43	3,314.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED PARTS	New	50.00	40.00
2	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS	New	120.00	80.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	140.00	30.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	200.00	120.00
5	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,500.00	800.00
6	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,200.00	600.00
7	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	180.00	30.00
Gross Labour Cost (\$\$)			3,390.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >