



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: RODERIC YUEN

Ref: CS/INC23004709/Uqy3m4

Date: 30/06/2023

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBL 5003Y	<b>Veh. Inspected</b>	YQ 5216B
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1221874-001	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HAZALYSA BINTE IBRAHIM	<b>Assign Date</b>	09/05/2023

#### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MITSUBISHI CANTER FEB21 (M)	<b>c.c</b>	2998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2021
<b>Chassis No.</b>	FEB21EA35514	<b>Colour</b>	WHITE
<b>Odometer</b>	39772 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/85 R15	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	195/85 R15	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	195/85 R15 (D/D)	YOKOHAMA	6/6 mm
<b>L/H Rear Tyre</b>	195/85 R15 (D/D)	YOKOHAMA	6/6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

<b>Accident Date</b>	04/05/2023	<b>Inspect Date / Time</b>	09/05/2023 ( 10:52 AM )
<b>Survey held at</b>	STYTECH AUTO PTE LTD 2 KAKI BUKIT AVENUE 2 #02-30 KAKI BUKIT AUTOHUB SINGAPORE 417921		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **15 Working Days**