5/17/23, 4:54 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

Our File No: CS/CTI23004715/KVP3M4
3 Anson Road, #16-00 Springleaf Tower

Singapore 079909 Date: 17/05/2023

REFERENCE

Insured/Claimant: . -- AVENUE ENGINEERING PTE

LTD

Policy No: DMCVSNA00020052303

Date of Loss: 05/05/2023 Nature of OD Claim No: SNM23D203249/C01/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP2049S

Make & Model: HINO XZU710R-HKFMS3, 4.0 D (M) Engine No: N04CUS27097

Reg. Date: 15/04/2016 (Man. Year: 2016) Chassis No: JHHUCS3HX0K016844

Colour: White Odometer: 235793 km

Engine Capacity: 4009 cc

Market Value/New Car

Price:

S\$52,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00R16 Rear Tyre Size: 7.00R16 (D)
Front Left Side: OTANI 8 mm Rear Left Side: Pirelli 2/2 mm
Front Right Side: OTANI 8 mm Rear Right Side: Pirelli 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	600.00	-600.00	
Nett Amount (S\$)	0.00	-600.00	600.00	

INSPECTION

Date of Assignment: 09/05/2023 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

LAI HUAT (MENG KEE) MOTOR PTE LTD

Date Inspected: 10/05/2023 Inspected At: 160 SIN MING DRIVE #04-01/02

SIN MING AUTOCITY SINGAPORE 575722

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value : \$52,000.00 OMV : \$27,086.00

PARF Rebate (1): \$0

Quota Premium Paid: \$19,225.00 \$5,650.00 COE Rebate (2): Total Rebate (1) + (2) = : \$5,650.00

The total amount incurred will be Market Value \$52,000.00 minus Total Rebate \$5,650.00 = \$46,350.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

5/17/23, 4:54 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 17 May 2023)

Parts: N/A HINO XZU710R-HKFMS3 4.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YP2049S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

5/17/23, 4:54 PM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >