

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23004716/AWP3Q2**Date:** 25/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00075202200
<b>Claimant Vehicle No :</b>	GBJ2673T	<b>Insured Vehicle No :</b>	YQ7226J
Date of Loss:	15/04/2023	Nature of Claim:	TP
		Claim No:	SNM23D202804/C02/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBJ2673T</b>	Engine No:	1KD2840827
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	JTFHT02PX00247571
Reg. Date:	25/02/2019 (Man. Year: 2018)	Odometer:	98280 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,384.87	1,599.30	1,785.57	52.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	860.00	990.00	53.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,234.87</b>	<b>2,459.30</b>	<b>2,775.57</b>	<b>53.02</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,950.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,234.87</b>	<b>1,950.00</b>	<b>3,284.87</b>	<b>62.75</b>

**INSPECTION**

Date of Assignment:	08/05/2023	
Date Inspected:	09/05/2023 Inspected At:	Sin Yu Sin Workshop (HQ) 1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit) Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 23 May 2023)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBJ2673T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	541.20 FL	*541.20 FL
2	1		*FRONT BUMPER SIDE HOLDER	Cracked	66.50 FL	*66.50 FL
3	1		*FRONT BUMPER SIDE GRILLE	Cut	62.10 FL	*62.10 FL
4	1		*HEADLAMP	Cracked	745.20 FL	*745.20 FL
5	1		*AIR CLEANER BOX	Cracked	637.40 FL	*637.40 FL
6	1		*FRONT DOOR	Repair	1,438.50 FL	*- FL
7	1		*FRONT DOOR LOCK	Not Necessary	282.50 FL	*- FL
8	1		*FRONT DOOR WEATHERSTRIPE	Not Necessary	281.50 FL	*- FL
9	1		*FRONT DOOR HINGE LOWER	Not Necessary	131.10 FL	*- FL
10	1		*FRONT STEP PANEL GARNISH	Not Necessary	220.50 FL	*- FL
11	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
12	1		*FRONT DOOR COMPANY ADDRESS STICKER	Necessary	30.00 FS	*30.00 FS
13	1		*SET FRONT STEP PANEL GARNISH CLIPS	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,486.50</b>	<b>2,112.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,101.63	513.10
<b>Total Parts (\$\$)</b>	<b>3,384.87</b>	<b>1,599.30</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING REMOVE AND REFIT PARTS	New	800.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	700.00	400.00
3	WIRING CHECK	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	30.00
5	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,850.00</b>	<b>860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >