

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23004726/UVP3M4**Date:** 22/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00276762201		
Claimant Vehicle No :	SGL9119L	Insured Vehicle No :	SLD6599L		
Date of Loss:	04/05/2023	Nature of Claim:	TP	Claim No:	SNM23D203225/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGL9119L	Engine No:	70815280B47D20B
Make & Model:	BMW 725D, 2.0 EXCLUSIVE AUTO (A)	Chassis No:	WBA7C02060BA25492
Reg. Date:	30/08/2019 (Man. Year: 2018)	Odometer:	76039 km
Colour:	Brown		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50R18	Rear Tyre Size:	245/50R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,670.70	3,848.44	5,822.26	60.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	820.00	1,700.00	67.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,190.70	4,668.44	7,522.26	61.70
Approved Total (Overridden) (\$\$)		3,700.00		
Nett Amount (\$\$)	12,190.70	3,700.00	8,490.70	69.65

INSPECTION

Date of Assignment:	09/05/2023		
Date Inspected:	10/05/2023	Inspected At:	HUAT HOCK MOTOR WORKSHOP BLK 3012 BEDOK NORTH AVE 4 BEDOK INDUSTRIAL PARK E #01-2054 SINGAPORE 489978
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2023)
Parts:	143	BMW 725D 2.0 EXCLUSIVE AUTO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGL9119L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Dented/Deformed	2,698.32 F	*2,102.00 FL
2	1	*REAR BUMPER SIDE RETAINER RH	Not Necessary	289.65 F	*- FL
3	1	*REAR BUMPER TOP RETAINER	Cracked	198.20 F	*198.20 FL
4	1	*REAR BUMPER REFLECTOR RH	Cracked	68.15 F	*68.15 FL
5	1	*REAR BUMPER REFLECTOR CHROME MOULDING RH	Serviceable	277.14 F	*- FL
6	1	*REAR BUMPER REINFORCEMENT BEAM	Bent	890.19 F	*605.12 FL
7	1	*REAR BUMPER REINFORCEMENT BEAM BRACKET	Cracked	151.95 F	*151.95 FL
8	1	*REAR BUMPER CHROME RH	Cracked	540.35 F	*366.01 FL
9	1	*REAR BUMPER CENTER CHROME MOULDING	Scratched	336.95 F	*292.45 FL
10	1	*REAR BUMPER REVERSE SENSOR 2PIECES	Malfunction (1Piece Only)	737.00 F	*225.00 FL
11	2	*REAR BUMPER REVERSE SENSOR HOLDER	Not Necessary	91.20 F	*- FL
12	2	*REAR EXHAUST PIPE RUBBER HOLDER	Not Necessary	40.70 F	*- FL
13	1	*REAR KICK SENSOR	Not Necessary	650.90 F	*- FL
14	1	*SET REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
15	1	*REAR EXHAUST PIPE AND BOX	Not Necessary	1,680.00 FS	*- FS
16	1	*REAR EXHAUST CHROME TIP RH	Not Necessary	980.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,670.70	4,048.88
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	200.44
Total Parts (\$\$)	9,670.70	3,848.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT ANTI-RUST TREATMENT	New	150.00	0.00
2	REMOVE AND INSTALL NEW REVERSE SENSOR	New	120.00	50.00
3	REWIRING TO FACILITATE REPAIRS	New	120.00	20.00
4	REMOVE AND REFIT EXHAUST PIPE	New	280.00	0.00
5	LABOUR TO REMOVE AND REPLACE DAMAGED PARTS, INCLUDING REFITTING AND REPOSITIONING OF REPLACED PARTS	New	900.00	400.00
6	SPRAY PAINTING MATERIALS AND RESPRAY OF ALL AFFECTED AND REPLACED PARTS NECESSARY FOR PAINTWORK	New	950.00	350.00
Gross Labour Cost (S\$)			2,520.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >