

AXA Ins. Michael  
8 Shenton Way  
#27-01 AXA Tower  
Spore 068811

Date: 4/5/23

Attn.: Motor Claims Department

Dear Sir/Madam

RE: Accident involving vehicles GRH 1043D & SEC 8301T

On 3/5/23 at BK 620 Honggang AVE & Ceylon

It is in my opinion that the above mentioned accident was caused solely by the negligence of the driver of the vehicle no: SEC 8301T

As the above vehicle was insured by your insurance company at the material time of the accident. I would appreciate that you could kindly arrange your surveyor to survey my vehicle soonest possible at the following address :-

Kan Fook Sing Motor Workshop  
BK 8 JTC Defu Industrial City  
#04-29 Defu South St-1  
Spore 53375  
Tel:- 67479560

Thank you

Yours faithfully





# 簡福星摩多工廠

## KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

AXA INSURANCE PTE LTD

DATE : 03-05-2023

8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

VEHICLE NO. : GBH1043D

ACCIDENT DATE : 03-05-2023 11:00

THIRD PARTY REF. : SHC8301T

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE GBH1043D TOYOTA DYNA

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
SPECIAL NETT ITEMS			
1	1	SIDE GATE LOGO RH	500.00
2	1	SIDE GATE WOODEN BLOCK	500.00
TOTAL ( C )			1,000.00

### LABOUR CHARGES

1	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	450.00
2	1	SPRAYPAINTING CHARGES	450.00
TOTAL ( D )			900.00
ESTIMATE TOTAL			1,900.00