



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 2147R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FENDER F RH (SN)	TO REPAIR SEE LABOUR	277.50	-
1	FENDER F LH (SN)	NOT NECESSARY	277.50	-
1	HOOD COMPL F (SN)	NOT NECESSARY	740.00	-
1	COVER ASSY FEN UPRH (SN)	DEFORMED	19.10	19.10
1	COVER ASSY FEN UPLH (SN)	NOT NECESSARY	18.50	-
1	BUMPER PUNCHING F OBK FOR H/W (SN)	DEFORMED	610.50	610.50
1	ENR ABSORB FOAM FEXP (SN)	NOT NECESSARY	59.20	-
1	BRKT CORNER F FHIRH (SN)	DEFORMED	33.30	33.30
1	BRKT CORNER F FHILH (SN)	NOT NECESSARY	33.30	-
1	BRKT SD F RH (SN)	NOT NECESSARY	18.50	-
1	BRKT SD F LH (SN)	NOT NECESSARY	18.50	-
1	BEAM COMPL F EU (SN)	NOT NECESSARY	296.00	-
1	COVER HOOK F OBK FHI (SN)	NOT NECESSARY	5.60	-
1	FRONT RESIN UNDER GUARD OBK (SN)	NOT NECESSARY	270.00	-
1	LAMP ASSY HEAD RHS (SN)	CRACKED	1,870.00	1,870.00
1	LAMP ASSY HEAD RLA (SN)	NOT NECESSARY	1,870.00	-
1	NOZZLE H L WASHERRH (SN)	NOT NECESSARY	92.50	-
1	NOZZLE H L WASHERLH (SN)	NOT NECESSARY	92.50	-
1	NOZZLE COVER ASSYOBR (SN)	NOT NECESSARY	55.50	-
1	NOZZLE COVER ASSYOBL (SN)	NOT NECESSARY	55.50	-
1	GRILLE ASSY F NA (SN)	NOT NECESSARY	703.00	-
1	ORNAMENT F 6KA (SN)	NOT NECESSARY	74.00	-
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			7,590.50	2,552.90
LABOUR				
REPLACE FRT HOOD, FRT BUMPER, ENERGY ABSORBER, BUMPER BEAM, LH FENDER & RH FENDER. INCLUSIVE OF THE REPAIR OF FENDER F RH.			3,500.00	1,500.00
RESPRAY FRT HOOD, FRT BUMPER, BUMPER BEAM, LH FENDER & RH FENDER.			3,000.00	1,820.00
TO CONDUCT FRONT LIGHTING TEST.			50.00	50.00

Report Ref No. CS/FCI23004735/Tqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REFIX FRONT HEADLAMP WASHER & PIPING.		150.00	150.00
	FAULT DIAGNOSTIC (RESET).		280.00	280.00
			6,980.00	3,800.00
GRAND TOTAL			14,570.50	6,352.90
RECOMMENDED COST OF REPAIRS				6,352.90

Report Ref No. CS/FCI23004735/Tqy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.