



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 2886R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE (N)	BADLY DENTED	1,177.00	1,177.00
1	REAR TAILGATE "MITSUBISHI" EMBLEM (N)	NECESSARY	48.00	48.00
1	REAR TAILGATE "L200" EMBLEM (N)	NECESSARY	30.00	30.00
1	REAR TAILGATE "SPORTERO" EMBLEM (N)	NECESSARY	58.00	58.00
1	REAR TAILGATE "DHD" EMBLEM (N)	NECESSARY	65.00	65.00
1	REAR TIPPER SIDE PANEL (INNER) - RH (N) (DENTED)	OLD DAMAGED	1,880.00	-
1	REAR TAIL LAMP PANEL - RH (N) (DENTED)	OLD DAMAGED	210.00	-
1	REAR TIPPER SIDE PANEL (OUTER) - RH (N) (DISTORTED)	OLD DAMAGED	1,950.00	-
1	REAR TIPPER PANEL (N) (BENT) (NPA)	OLD DAMAGED	-	-
	LESS 10% DISCOUNT		-541.80	-137.80
			4,876.20	1,240.20
<u>SPECIAL NETT ITEMS</u>				
1	70KM/H STICKER (SN)	NECESSARY	20.00	10.00
			20.00	10.00
<u>LABOUR</u>				
	SPRAY PAINTING.		980.00	600.00
	LABOUR CHARGE.		1,100.00	600.00
	TUFF COAT.		100.00	30.00
	WIRING.	NOT NECESSARY	30.00	-
			2,210.00	1,230.00
GRAND TOTAL			7,106.20	2,480.20
RECOMMENDED COST OF REPAIRS				2,480.20

Report Ref No. CS3/SMR23003694/Uqy3e2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.