

ASS. REC. BY:

REF:

TJ / 23004742/Ky

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / Maybe part by part.

19/8 @ 1637.41 Cnhu

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

S - RS. SI

Fees

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email:

tanpw@cdge.com.sg; kelvinsukwen@cdge.com.sg; oisunpin@cdge.com.sg; joharibh@sparkcarcare.com; kristytay@sparkcarcare.com

TP INSURER: India International Insurance Pte Ltd (HQ)
TAN HOE ANN JACOB

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	23/04/2023
Vehicle Reg. No.:	SJP8998R	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HONDA ACCORD, 2.0 VTIS 5AT (A)	Vehicle Reg. Date:	20/07/2016
Vehicle Colour:	WHITE		
Engine No:	R20Z21600031	Chassis No:	MRHCR1630GP000011
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	2 days		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

*Not wither
\$1637.41
Repair After Claim*

COST OF CLAIMS

	Amount
Parts	7,303.67
Miscellaneous Items	11.00
Labour	1,880.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,194.67
+ GST 8.00% (S\$)	735.57
Nett Amount (S\$)	9,930.24

This claim is handled by: PATRICK TIA JEE KIANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 May 2023)
Parts: 143	HONDA ACCORD 2.0 VTIS 5AT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SJP8998R/08/05/2023 13:57	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*REAR BOOT LID	0.00	0.00	*1,314.56 F	X
2	1		*REAR BOOT LID WEATHERSTRIP	0.00	0.00	*110.76 F	X
3	1		*REAR BOOT LID LOCK	0.00	0.00	*151.06 F	X
4	1		*REAR BOOT LID EMBLEM	0.00	0.00	*46.54 F	X
5	1		*REAR BOOT LID ACCORD WORDING	0.00	0.00	*36.40 F	1
6	1		*REAR BUMPER	0.00	0.00	*885.17 F	✓
7	1		*REAR BUMPER REINFORCEMENT	0.00	0.00	*436.80 F	X
8	10		*REAR BUMPER CLIP	0.00	0.00	*50.00 F	✓
9	2		*REAR BUMPER SIDE RETAINER	0.00	0.00	*50.70 F	✓
10	1		*REAR BUMPER CHROME MOULDING	0.00	0.00	*306.41 F	✓
11	1		*REAR BUMPER REFLECTOR RH	0.00	0.00	*56.65 F	X
12	2/1		*REAR BUMPER SENSOR CENTER	0.00	0.00	*771.42 F	✓
13	2		*REAR TAIL LAMP	0.00	0.00	*1,869.92 F	X

F=Franchise part.

Sub Total (S\$)	6,086.39
+ Margin on L,N Items 20.00% (S\$)	1,217.28
Total Parts (S\$)	7,303.67

ComfortDelGro Engineering Pte Ltd/SJP8998R/08/05/2023 13:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	201 100.00
2	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	801 120.00
3	PANEL BEATING,KNOCKING AND STRIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL PF PARTS , ADJUST AND REALIGN THE SAME	New	2001 580.00
4	PUTTY AND SPARY PANTING OF THE AFFECTED PORTION.	New	2501 900.00
5	TO RUST PROOF THE AFFECTED AREAS.	New	120 180.00 X
Gross Labour Cost (S\$)			1,880.00

ComfortDelGro Engineering Pte Ltd/SJP8998R/08/05/2023 13:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >