

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG23004773/AVP3E2**Date:** 03/08/2023**REFERENCE**

Insured/Claimant: CLARA YEO XINYING (CLARA YANG XINYING)

Policy No: 7210111670

Date of Loss: 23/04/2023

Nature of Claim: OD Claim No: 7878392307SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNC1899K**

Make & Model: AUDI A5, 2.0 SPORTBACK TFSI S TRONIC (A)

Engine No: DEM034231

Reg. Date: 23/09/2021 (Man. Year: 2021)

Chassis No: WAUZZZF57NA002203

Colour: White

Odometer: 21456 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$185,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 245/40 R18

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,242.00	2,258.00	12,984.00	85.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,972.00	2,272.00	3,700.00	61.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,214.00	4,530.00	16,684.00	78.65
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	19,614.00	2,930.00	16,684.00	85.06
+ GST 8.00/8.00% (S\$)	1,569.12	234.40	1,334.72	85.06
Nett Amount (S\$)	21,183.12	3,164.40	18,018.72	85.06

INSPECTION

Date of Assignment: 10/05/2023

Date Inspected: 10/05/2023

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,642.00 FS	*2,113.60 FS
2	1		*FRONT BUMPER SECURING STRIP	Not Necessary	42.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	310.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE -LH	Not Necessary	53.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Not Necessary	159.00 FS	*- FS
6	1		*FRONT BUMPER TRIM -LH	Not Necessary	57.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION -LH	Not Necessary	43.00 FS	*- FS
8	1		*FRONT FENDER -LH	Repair	1,258.00 FS	*- FS
9	1		*FRONT FENDER CLOSING ELEMENT -LH	Not Necessary	88.00 FS	*- FS
10	1		*FRONT FENDER BRACKET -LH	Not Necessary	44.00 FS	*- FS
11	6		*FRONT FENDER RIVET	Not Necessary	24.00 FS	*- FS
12	1		*FRONT FENDER BRACE -LH	Not Necessary	140.00 FS	*- FS
13	1		*FRONT FENDER CHROME TRIM -LH	Necessary	181.00 FS	*144.40 FS
14	1		*FRONT WHEEL HOUSING LINER -LH	Not Necessary	322.00 FS	*- FS
15	1		*FRONT WHEEL SPOILER	Not Necessary	87.00 FS	*- FS
16	1		*FRONT FENDER LEDGE COVER -LONG	Not Necessary	42.00 FS	*- FS
17	1		*FRONT FENDER LEDGE COVER -LH SHORT	Not Necessary	19.00 FS	*- FS
18	1		*FRONT HEADLAMP COVER -LH	Not Necessary	52.00 FS	*- FS
19	1		*HEADLIGHT -LH	Not Necessary	8,666.00 FS	*- FS
20	1		*LIFT CYLINDER -LH	Not Necessary	230.00 FS	*- FS
21	1		*FRONT PARKING AID SENSOR -LH	Not Necessary	272.00 FS	*- FS
22	4		*FRONT PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
23	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	15,242.00 2,258.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER AND LHS HEADLIGHT RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
4	TO RESPRAY FRONT BUMPER AND FRONT FENDER	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,972.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >