6/6/23, 11:02 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III23000903/WQY3E2-1

87544 km

Date: 06/06/2023

Odometer:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_02

Claimant Vehicle

GBJ1241M

Insured Vehicle No: SLM2908H

NO.

Date of Loss: 26/01/2023 Nature of Claim: TP Claim No: MFL2023D0001149

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ1241M

 Make & Model:
 TOYOTA HIACE, 2.8 D (A)
 Engine No:
 1GD8353284

 Reg. Date:
 11/01/2019 (Man. Year: 2018)
 Chassis No:
 GDH2012003889

Colour: White

Engine Capacity: 2754 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R15 Rear Tyre Size: 195/80 R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,137.00	555.82	581.18	51.12
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,100.00	550.00	550.00	50.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	2,237.00	1,105.82	1,131.18	50.57
	Approved Total (Overridden) (S\$)		850.00		
	Nett Amount (S\$)	2,237.00	850.00	1,387.00	62.00

INSPECTION

Date of Assignment: 10/05/2023

MOTORMED PTE LTD (HQ)

Date Inspected: 14/02/2023 Inspected At: 8 KAKI BUKIT AVE 4, #02-14/44 PREMIER @KAKI

BUKIT

Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: Mohdakid Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/6/23, 11:02 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Jun 2023)

Parts: N/A TOYOTA HIACE 2.8 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBJ1241M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Dented / Deformed	483.20 FL	*483.20 FL
2	4		*RR BUMPER CLIP	Necessary	12.80 FL	*12.80 FL
3	2		*RR BUMPER SIDE SUPPORT R/L	Necessary	46.80 FL	*46.80 FL
4	1		*RR WHEEL RIM COVER RH	Dented / Defaced	198.30 FL	*198.30 FL
5	1		*RR AXLE SHAFT RH	Not Necessary	774.90 FL	*- FL
6	1		*RR BODY PANEL RH (NPA)	Not Necessary	0.00 FL	*- FL
F=Fra	F=Franchise part. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 25.00/25.00% (S\$)			1,516.00 379.00	741.10 185.28	
				Total Parts (S\$)	1,137.00	555.82
			Report was unsubmitted	d during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	500.00	250.00
2	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA	New	500.00	300.00
3	TO CONDUCT WHEEL ALIGNMENT (2X)	New	100.00	0.00
	Gross Labour Cost (S\$)		1,100.00	550.00
	Report was unsubmitted during this	s print-out.		

< END OF ESTIMATES >