

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	HSBC LIFE (SINGA	APORE) PTE LTD	Ref:	CC4/HSB23004782/Upa3q2	
	10 MARINA BOULE #48-01 MARINA BA 2SINGAPORE 0189	AY FINANCIAL CENTRE TOWER	Date:	27/06/2023	
	ATTN:GARNET		Code:	HSB	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 3298H	Veh. Inspected	SMS 5340G	
	Policy No.	P2478220	Coverage (\$)	0.00	
	Claim No.	S3M04MD2	Excess (\$)	0.00	
	Assign From		Assign Date	10/05/2023	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HARRIER (A)	c.c	1986	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	ZSU600051330	Colour	WHITE	
	Odometer	141802 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	235/55 R18	MICHELIN	6 mm	
	L/H Front Tyre	235/55 R18	MICHELIN	6 mm	
	R/H Rear Tyre	235/55 R18	MICHELIN	6 mm	
	L/H Rear Tyre	235/55 R18	MICHELIN	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	08/05/2023	Inspection Date	10/05/2023	
	Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD			
		1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
	N)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				