

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23004784/KNP3Q2**Date:** 30/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00117092202		
Claimant Vehicle No :	SJM7432D	Insured Vehicle No :	GBE2621U		
Date of Loss:	04/05/2023	Nature of Claim:	TP	Claim No:	SNM23D203238/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM7432D	Engine No:	G4FC8U565721
Make & Model:	HYUNDAI HD AVANTE, 1.6 (A)	Chassis No:	KMH DU41BR9U648195
Reg. Date:	15/01/2009 (Man. Year: 2008)	Odometer:	237791 km
Colour:	Metallic Gold		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	APLUS 7 mm	Rear Left Side:	LAUFENN 4 mm
Front Right Side:	APLUS 7 mm	Rear Right Side:	LAUFENN 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,012.80	3,107.20	3,905.60	55.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,330.00	1,070.00	44.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,412.80	4,437.20	4,975.60	52.86
Approved Total (Overridden) (S\$)		3,550.00		
Nett Amount (S\$)	9,412.80	3,550.00	5,862.80	62.29

INSPECTION

Date of Assignment:	10/05/2023	Authorize Workshop Pte Ltd (HQ)
Date Inspected:	16/05/2023	Inspected At: 160 Sin Ming Drive, #03-19 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2023)
Parts:	143	HYUNDAI HD AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM7432D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,981.20 FL	*1,021.30 FL
2	2		*BONNET HINGE L/R	Repair	175.20 FL	*- FL
3	1		*BONNET LOCK	Repair	102.50 FL	*- FL
4	1		*BONNET LOCK GARNISH	Serviceable	28.30 FL	*- FL
5	1		*HEADLAMP L/R	O/S Cracked	1,188.40 FL	*594.20 FL
6	1		*HEADLAMP LOWER BRACKET RH	Serviceable	98.50 FL	*- FL
7	1		*FRT FENDER L/R	N/S Repair / O/S Bent	1,937.60 FL	*845.20 FL
8	2		*FRT FENDER VVTI EMBLEM	Necessary	76.20 FL	*76.20 FL
9	1		*FRT FENDER INNER LINER RH	Serviceable	98.60 FL	*- FL
10	1		*WINDSCREEN WASHER TANK	Serviceable	218.50 FL	*- FL
11	1		*FRT BUMPER	Bent / Cracked	431.90 FL	*431.90 FL
12	1		*FRT BUMPER SIDE HOLDER RH	Distorted	32.00 FL	*32.00 FL
13	1		*FRT BUMPER INNER FOAM	Serviceable	162.60 FL	*- FL
14	1		*FRT BUMPER REINFORCEMENT	Repair	282.60 FL	*- FL
15	1		*FRT BUMPER FOG LAMP	Serviceable	271.40 FL	*- FL
16	1		*FRT BUMPER UNDERSHIELD	Serviceable	82.60 FL	*- FL
17	1		*FRT GRILLE	Serviceable	352.20 FL	*- FL
18	1		*FRT SUPPORT PANEL	Cracked	783.20 FL	*783.20 FL
19	1		*SET FRT BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
20	1		*SET FRT FENDER LINER CLIPS	Necessary	35.00 FS	*35.00 FS
21	1		*SET FRT BUMPER UNDERSHIELD CLIPS	Not Necessary	40.00 FS	*- FS
22	1		*FRT ROAD TIRE RH	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,673.50	3,864.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,660.70	756.80
Total Parts (\$\$)	7,012.80	3,107.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTINGS	New	50.00	20.00
2	TO REMOVE ,REINSTAL RADIATOR ,A/C CONDENSER TO FACILITATE REPAIRS	New	150.00	50.00
3	TO RECHARGE AIR CON GAS ,TOP UP COOLANT	New	120.00	100.00
4	TO REMOVE ,REPAIR & REPLACE DAMAGED BODYPARTS ,REALIGN BODYWORK AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
5	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	1,000.00	600.00
6	RUST PROOFING ON AFFECTED PORTIONS	New	80.00	60.00
Gross Labour Cost (\$\$)			2,400.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >