

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	HSBC LIFE (SINGAPORE) PTE LTD		Ref:	CS3/HSB23004786/Rqp3e2	
		EVARD #48-01 MARINA BAY RE TOWER 2 SINGAPORE	Date:	16/05/2023	
	ATTN: ANG YVON	NE	Code:	HSB	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 8544D	Veh. Inspected	SJW 7277H	
	Policy No.	VFX/P2419140	Coverage (\$)	0.00	
	Claim No.	S3M04MCZ	Excess (\$)	0.00	
	Assign From	ANG YVONNE	Assign Date	10/05/2023	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA WISH 1.8X A	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	ZGE200021877	Colour	WHITE	
	Odometer	325197 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	MICHELIN	6 mm	
	L/H Front Tyre	205/60 R16	MICHELIN	6 mm	
	R/H Rear Tyre	205/60 R16	MICHELIN	6 mm	
	L/H Rear Tyre	205/60 R16	MICHELIN	6 mm	
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.			
5.	General Information				
	Accident Date	08/05/2023	Inspect Date / Time	10/05/2023 (03:30 PM)	
	Survey held at	7 Soon Lee Street, #01-32 Ispace	e, Singapore 627608		
	Repairer	SK GARAGE			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/HSB23004786/Rqp3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser