

ASS. REC. BY:

REF:

12 / 23004793/ky

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: B133k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMH 5252k Yr Regn: 01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: NIS Elgrand c.c. 2488Colour: M. Silver AC: Insured / Std / NI / NASp. Reading: 73036 T/Radio: Insured / Std / NI / NAEng/No: JNITBAE 528 080 5003C/No: TOBARVWE 52207Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 235/55R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 7/5/23D.O.I. 10/5/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 EM not ready

7/6 L18up & 7300h Cash

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: NISSAN ELGRAND
Engine/Chassis No.:
Date of accident: 07.05.23
Damaged area: Rear

Date: 09/05/2023
Claim Type: TP
VRN: SMH5252K

Not Authorized
L1 Surp & 7300h
Resurvey After Paint
6 days

List Items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear bumper <i>763</i>	<i>PR</i> 1	\$ 1,659.20	\$ 1,659.20	✓
2	Rear bumper top bracket	<i>R</i> 2	\$ 110.70	\$ 221.40	X
3	Rear bumper side retainer	<i>OLSDR</i> 2	\$ 98.00	\$ 196.00	X
4	Rear bumper reflector <i>0147.90</i>	<i>OLSDR</i> 2	\$ 223.00	\$ 446.00	X
5	Tailgate <i>2572</i>	<i>PR</i> 1	\$ 3,240.00	\$ 3,240.00	✓
6	Tailgate outer chrome moulding	<i>PR</i> 1	\$ 580.80	\$ 580.80	X
7	Tailgate center lamp	<i>PR</i> 1	\$ 1,325.00	\$ 1,325.00	X
8	Tailgate lock mechanism <i>385</i>	<i>PR</i> 1	\$ 800.20	\$ 800.20	✓
9	Tailgate lock cover	<i>PR</i> 1	\$ 45.90	\$ 45.90	X
10	Tailgate lock release switch	<i>PR</i> 1	\$ 279.70	\$ 279.70	X
11	Tailgate "NISSAN" logo	<i>PR</i> 1	\$ 89.00	\$ 89.00	X
12	Tailgate "HIGHWAY STAR" emblem	<i>PR</i> 1	\$ 98.00	\$ 98.00	X
13	Rear parking aid wire harness	<i>PR</i> 1	\$ 453.00	\$ 453.00	X
14	Rear lock sensor antenna	<i>370.50 PR</i> 1	\$ 412.00	\$ 412.00	✓
15	Tailgate inner trim board <i>580.50</i>	<i>PR</i> 1	\$ 983.20	\$ 983.20	✓
16	Tailgate inner handle	<i>PR</i> 1	\$ 112.30	\$ 112.30	X
17	Tailgate weatherstrip <i>239.60</i>	<i>OLSDR</i> 1	\$ 373.00	\$ 373.00	<i>508.50 119.80</i>
18	Tailgate rubber stopper	<i>PR</i> 2	\$ 36.60	\$ 73.20	X
19	Tailgate hinge	<i>R</i> 2	\$ 87.20	\$ 174.40	X
20	Tailgate damper	<i>PR</i> 2	\$ 141.10	\$ 282.20	X
21	Tailgate windscreen glass moulding	<i>PR</i> 1	\$ 390.40	\$ 390.40	X
22	Taillamp	<i>PR</i> 2	\$ 677.00	\$ 1,354.00	X
23	End panel <i>742.40</i>	<i>PR</i> 1	\$ 812.00	\$ 812.00	✓
24	End panel top garnish <i>216.80</i>	<i>PR</i> 1	\$ 418.00	\$ 418.00	✓
25	Floor panel	<i>R</i> 1	\$ 923.00	\$ 923.00	X
26	Taillamp lower side cover	<i>PR</i> 2	\$ 421.00	\$ 842.00	X
27	Taillamp lower side garnish retainer	<i>PR</i> 2	\$ 78.00	\$ 156.00	X
28	Rear bumper tow hook cover	<i>PR</i> 2	\$ 92.00	\$ 184.00	X
29	Floor panel top board	<i>PR</i> 2	\$ 298.00	\$ 596.00	X
30	Rear reinforcement	<i>PR</i> 1	\$ 594.00	\$ 594.00	✓
31	Rear reinforcement side bracket	<i>PR</i> 2	\$ 145.00	\$ 290.00	✓
32	Rear bumper side sponge	<i>PR</i> 2	\$ 75.00	\$ 150.00	X
33	Rear bumper center sponge	<i>PR</i> 1	\$ 178.00	\$ 178.00	✓
34	Rear signal lamp <i>262.40</i>	<i>OLSDR</i> 2	\$ 395.00	\$ 790.00	X
35	Rear bumper inner side garnish	<i>PR</i> 2	\$ 49.00	\$ 98.00	X
36	Tailgate auto close sensor	<i>PR</i> 1	\$ 1,198.00	\$ 1,198.00	X
Subtotal				\$ 20,817.90	
List discount				10.00%	
Total				\$ 18,736.11	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Sundries <i>na</i>	1	\$ 50.00	\$ 50.00
2	Rear bumper clips <i>na</i>	12	\$ 5.50	\$ 66.00
3	Tailgate outer chrome moulding clips <i>na</i>	6	\$ 5.50	\$ 33.00
4	Tailgate inner trim board clips <i>na</i>	12	\$ 5.50	\$ 66.00
5	Tailgate windscreen sealant <i>na</i>	1	\$ 100.00	\$ 100.00
6	End panel sealant <i>na</i>	1	\$ 100.00	\$ 100.00
7	End panel top garnish clips <i>na</i>	6	\$ 5.50	\$ 33.00
8	Floor panel sealant <i>na</i>	1	\$ 120.00	\$ 120.00
9	Reverse sensor <i>part</i>	2	\$ 180.00	\$ 360.00
10	Reverse camera <i>sm</i>	1	\$ 550.00	\$ 550.00
Total				\$ 1,478.00

X
✓
X
✓
405N
305N
—
X
2005N
X

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	8	\$ 1,600.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	To reset tailgate auto lock mechanism.	1	\$ 200.00
5	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00
6	Supply spray paint material and necessary items to respray affected area / panel.	7	\$ 1,400.00
7	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 3,600.00

700l
20l
60l
80l
120l
800l
60l

Estimate Grand Total	\$ 23,814.11
----------------------	--------------