

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG23004811/UYA3Q2
Date: 28/07/2023

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100429633-07
Claimant Vehicle No : SLP8358P **Insured Vehicle No :** GBE1778H
 Date of Loss: 10/05/2023 Nature of Claim: TP Claim No: 0819824123SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP8358P**
 Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR1824906
 Reg. Date: 31/08/2016 (Man. Year: 2016) Chassis No: JTDGG20W10J004918
 Colour: Silver Odometer: 142565 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,110.25	4,613.02	1,497.23	24.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,100.00	1,350.00	55.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,560.25	5,713.02	2,847.23	33.26
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	8,560.25	4,500.00	4,060.25	47.43
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
Nett Liability (S\$)		4,900.00		

INSPECTION

Date of Assignment: 11/05/2023
 Date Inspected: 11/05/2023 Inspected At: Leang Automotive (Kaki Bukit)
 #01-68
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Badly Dented	1,866.10 FL	*1,866.10 FL
2	1		*FRONT DOOR OUTER HANDLE O/S	Twisted / Damaged	266.10 FL	*266.10 FL
3	1		*FRONT DOOR INNER LOCK O/S	Damaged	509.10 FL	*509.10 FL
4	1		*FRONT DOOR INNER TRIM O/S	Not Necessary	788.10 FL	*- FL
5	1		*FRONT DOOR OUTER CHROME MOULDING O/S	Necessary	366.60 FL	*366.60 FL
6	1		*SET FRONT DOOR FRAME OUTER STICKER O/S	Necessary	60.00 FL	*60.00 FL
7	1		*FRONT DOOR GLASS REGULATOR O/S	Bent	366.10 FL	*366.10 FL
8	1		*FRONT DOOR GLASS REGULATOR MOTOR O/S	Damaged / Jammed	485.10 FL	*485.10 FL
9	1		*REAR DOOR O/S	Badly Dented	1,805.10 FL	*1,805.10 FL
10	1		*SET REAR DOOR FRAME OUTER BLACK STICKER O/S	Necessary	60.00 FL	*60.00 FL
11	1		*REAR DOOR OUTER CHROME MOULDING O/S	Necessary	366.50 FL	*366.50 FL
12	1		*REAR DOOR INNER LOCK O/S	Not Necessary	509.10 FL	*- FL
13	1		*CENTRE PILLAR O/S	Repair	699.10 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	8,147.00	6,150.70
- List Item Discount on L Items 25.00/25.00% (\$)	2,036.75	1,537.68
Total Parts (\$)	6,110.25	4,613.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	100.00	60.00
3	TO TRANSFER BOTH O/S DOOR MECHANISM	New	120.00	120.00
4	TO DIAGNOSTIC & REPROGARMME SYSTEM	New	180.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	800.00	300.00
6	TO PUTTY & SPRAY PAINTING	New	1,200.00	600.00
			Gross Labour Cost (S\$)	2,450.00
				1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >