

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS6/AIS23004815/CQP3M4**Date:** 27/06/2023**REFERENCE**

Insured/Claimant:	LOW ZHEN YANG	Policy No:	SP2001919392-01
Date of Loss:	08/05/2023	Nature of Claim:	OD
		Claim No:	202332008123

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM7407S	Engine No:	G4FGKU134763
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS (A)	Chassis No:	KMHD841CMKU902441
Reg. Date:	12/07/2019 (Man. Year: 2019)	Odometer:	60952 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,318.40	6,224.90	93.50	1.48
Miscellaneous Items	65.00	65.00	0.00	0.00
Labour	1,730.00	1,410.00	320.00	18.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,113.40	7,699.90	413.50	5.10
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	8,113.40	7,099.90	1,013.50	12.49
+ GST 8.00/8.00% (S\$)	649.08	567.99	81.09	12.49
Nett Amount (S\$)	8,762.48	7,667.89	1,094.59	12.49

INSPECTION

Date of Assignment:	10/05/2023	Present Location:	SME Motor Pte Ltd (Kaki Bukit) SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883
Date Inspected:	10/05/2023	Inspected At:	
Estimated Period of Repair:	5.0 days		

Adjuster: SIMON HO LEONG CHUAN**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2023)
Parts: 143	HYUNDAI AD AVANTE 1.6 GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM7407S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET (WCP)	Buckled	780.00 F	*780.00 F
2	2		*FRT BONNET HINGES (WCP)	Bent	110.00 F	*110.00 F
3	1		*FRT BONNET LOCK (WCP)	Not Necessary	95.00 F	*- F
4	1		*FRT GRILLE (WCP)	Cracked	580.00 F	*580.00 F
5	1		*GRILLE CENTRE LOGO (WCP)	Necessary	-	-
6	4		*GRILLE CLIPS (WCP)	Necessary	8.00 F	*8.00 F
7	1		*FRT BUMPER (WCP)	Broken	330.00 F	*330.00 F
8	1		*FRT BUMPER RETAINER (WCP)	O/S Bent/ N/S Not Necessary	40.00 F	*20.00 F
9	10		*FRT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
10	1		*FRT BUMPER INNER SPONGE (WCP)	Cracked	105.00 F	*105.00 F
11	1		*FRT BUMPER REINFORCEMENT (WCP)	Dented	380.00 F	*380.00 F
12	2		*HEADLAMP (WCP)	Cracked	1,720.00 F	*1,720.00 F
13	1		*HEADLAMP SUPPORT PANEL (WCP)	Cracked	350.00 F	*350.00 F
14	1		*HEADLAMP SUPPORT TOP GARNISH (WCP)	Cracked	85.00 F	*85.00 F
15	8		*TOP GARNISH CLIPS (WCP)	Necessary	16.00 F	*16.00 F
16	1		*AIRCON CONDENSER (WCP)	Dented	250.00 F	*250.00 F
17	1		*RADIATOR (WCP)	Dented	280.00 F	*280.00 F
18	1		*RH HEADLAMP BRACKET (WCP)	Cut	28.00 F	*28.00 F
19	1		*RH AIRCON SIDE DEFLECTOR (WCP)	Torn	40.00 F	*40.00 F
20	1		*FRT RH FENDER (WCP)	Bent	450.00 F	*450.00 F
21	1		*NUMBER PLATE GARNISH NO STOCK (WCP)	Cracked	-	*30.00 F
Supplementary #1						
22	1		*GRILLE REAR BRACKET RH (WCP)	Distorted	12.00 F	*12.00 F
23	1		*WASHER TANK (WCP)	Cut	65.00 F	*65.00 F

F=Franchise part.

Sub Total (S\$)	5,744.00	5,659.00
+ Margin on L,N Items 10.00/10.00% (S\$)	574.40	565.90
Total Parts (S\$)	6,318.40	6,224.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	NUMBER PLATE Cracked	40.00	40.00
2	1	RADIATOR COOLANT Necessary	25.00	25.00
			Sub Total (S\$)	65.00
				65.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	30.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	80.00
3	LABOUR CHARGE	New	700.00	600.00
4	SPRAY PAINTING	New	900.00	700.00
			Gross Labour Cost (S\$)	1,730.00
				1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >