

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/CTI22007208/KQY3M4  
**Date:** 03/08/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00017372100

Claimant Vehicle No : SLC3405M Insured Vehicle No : PA8827J

Date of Loss: 27/07/2022 Nature of Claim: TP Claim No: SNM22D205267/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC3405M**

Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGGH613519

Reg. Date: 11/05/2016 (Man. Year: 2016) Chassis No: KNAFX411MG5603732

Colour: Metallic Grey Odometer: 152173 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm

Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 28/07/2022

Date Inspected: 29/07/2022 Inspected At: SERVE YOU MOTOR PTE LTD (HQ)  
BLK 5033 ANG MO KIO INDUSTRIAL PARK 2, #01-265  
SINGAPORE 569536

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$8,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Aug 2022)
<b>Parts:</b>	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	<b>LKK Auto Consultants Pte Ltd/SLC3405M/03/08/2022 13:43</b>	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

**LKK Auto Consultants Pte Ltd/SLC3405M/03/08/2022 13:43.** Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

LKK Auto Consultants Pte Ltd/SLC3405M/03/08/2022 13:43. Not valid without Reference section.
--

< END OF ESTIMATES >