



Auto Consultants

Co.Reg no: 53439395X

VEHICLE INSPECTION REPORT

Our Ref: SLVDIR/22/07/003

Date: 28/07/2022

To: MR EE KIN CHEONG
Repairer Company: SERVE YOU MOTOR PTE LTD
Address: 5033 Ang Mo Kio Industrial Park 2 #01-265
Postal Code: 569536

REFERENCES

Claim Type:	THIRD PARTY	Date of Accident:	27/07/2022
Third party vehicle:	SLC3405M	Date of Inspection:	28/07/2022
Insured Vehicle:	NIL		

DAMAGED VEHICLE PARTICULARS

Registration Plate No:	SLC3405M	Engine Modification:	NIL
Model/ Make:	KIA Cerato Forte K3 1.6A EX	Pre-accident damage:	NIL
Date of Registration:	11/05//2016	General Condition:	Fair
Chassis No:	KNAFX411MG5603732	General Paint Colour:	Grey
Engine No:	G4FGGH613519	Steering:	Affected
Engine Capacity:	1591cc	Handbrake:	Good
Odometer No:	152173	Footbrake:	Good

TYRES CONDITION

Front Right

Make: Pirelli
Size: 205 55 R16 80%

Front Left

Make: Pirelli
Size: 205 55 R16 80%

Rear Right

Make: Pirelli
Size: 205 55 R16 80%

Rear Left

Make: Pirelli
Size: 205 55 R16 80%

The above percentages represent the remaining life of tyre treads

SL Auto Consultants

Accident Claims . Survey Services . Professional Advice

Add: 129 Lorong Ah Soo #05-352 Singapore 530129

Email: slautoconsultants@gmail.com / Mobile No: 90067276

VEHICLE REPAIR COST

Descriptions	Repairer SGD	Adjuster SGD
Parts	\$ 16,059.42	\$ 11,916.72
Special Nett	\$ 1,700.00	\$ 1,310.00
Labour	\$ 6,080.00	\$ 4,450.00
Calculated Cost SGD	<u>\$ 23,839.42</u>	<u>\$ 17,676.72</u>

Recommended Lump Sum Repair Cost SGD	\$ 14,141.38
Estimate Repair Duration	12 Working Days
Survey Inspection Location	SERVE YOU MOTOR PTE LTD
Survey Inspection Address	5033 Ang Mo Kio Industrial Park 2 #01-265 Singapore 569536

DESCRIPTION OF DAMAGE

LHS Front and Undercarriage Portion


REMARKS

We have inspected the actual damages found on the vehicle and recommended the replacement of parts and repairs accordingly. The estimated repair cost is \$14,141.38. The repairer has to agree to undertake the repairs at our adjusted lump sum amount of \$14,100.00.

We have not authorized the repair. Under normal circumstances, estimated 10 working days are required.

We are pleased to advise that the inspection work was carried out accordingly and hereby submit our Inspection Report.

The inspection was conducted on a "WITHOUT PREJUDICE" basis.



Automotive Appraiser: Samuel Phun

SL Auto Consultants
Accident Claims . Survey Services . Professional Advice
Add: 129 Lorong Ah Soo #05-352 Singapore 530129
Email: slautoconsultants@gmail.com / Mobile No: 90067276

ASSESSMENT REPORT FOR VEHICLE NO: SLC3405M**LIST ITEMS**

No	Qty	Description	CONDITION	REPAIRER		ADJUSTER	
				Amount SGD		Amount SGD	
1	1	Front Bumper	Cracked	\$	850.00	\$	850.00
2	1	Front Bumper Top Rubber	Necessary	\$	80.00	\$	80.00
3	2	Front Bumper Retainer	LHS Cracked/ RHS Necessary	\$	90.00	\$	90.00
4	1	Front Bumper Logo	Necessary	\$	48.00	\$	48.00
5	1	Front Bumper Grille	Deformed	\$	450.00	\$	450.00
6	1	Front Bumper Lower Grille	Deformed	\$	188.00	\$	188.00
7	1	Front Bumper LHS Side Cover	Deformed	\$	89.00	\$	89.00
8	1	Front Bumper LHS Fog Lamp	Cracked	\$	299.00	\$	299.00
9	1	Front Bumper Sponge	Serviceable	\$	116.00	\$	-
10	1	Front Bumper Reinforcement	Serviceable	\$	450.00	\$	-
11	1	Front Bonnet	Repair	\$	980.00	\$	-
12	2	Front Bonnet Hinges	Serviceable	\$	88.00	\$	-
13	6	Front Bonnet Stopper	Serviceable	\$	48.00	\$	-
14	1	Front Bonnet Lock	Serviceable	\$	149.00	\$	-
15	1	Front LHS Headlamp	Cracked	\$	998.90	\$	998.90
16	1	Front LHS Headlamp Bracket	Cracked	\$	85.00	\$	85.00
17	1	Front Support Panel	Cracked	\$	668.00	\$	668.00
18	1	Front Support Panel Top Garnish	Serviceable	\$	156.00	\$	-
19	1	Engine Diagnostic Socket	Cracked	\$	160.00	\$	160.00
20	1	Air Duct	Cracked	\$	119.00	\$	119.00
21	1	Air Resonator Box	Cracked	\$	188.00	\$	188.00
22	1	Front LHS Fender	Dented	\$	650.00	\$	650.00
23	1	Front LHS Fender Inner Panel	Dented	\$	551.00	\$	551.00
24	1	Front LHS Fender Inner Shield	Cracked	\$	174.00	\$	174.00
25	1	Front LHS Quarter Glass	Serviceable	\$	212.00	\$	-
26	1	Front LHS Door Assy	Repair	\$	998.00	\$	-
27	1	Front LHS Wing Mirror Assy	Grazed	\$	758.00	\$	758.00
28	1	Front 'A' Pillar	Repair	\$	1,018.00	\$	-
29	1	Front LHS Shock Absorber	Bent	\$	415.90	\$	415.90
30	1	Front LHS Shock Absorber Top Mtg	Necessary	\$	115.00	\$	115.00
31	1	Front LHS Shock Absorber Dust Cvr	Necessary	\$	68.00	\$	68.00
32	1	Front LHS Shock Absorber Stopper	Necessary	\$	50.00	\$	50.00
33	1	Front LHS Knuckle Arm	Distorted	\$	458.00	\$	458.00
34	1	Front LHS Wheel Bearing	Affected	\$	160.80	\$	160.80
35	1	Front LHS Wheel Hub	Distorted	\$	220.80	\$	220.80
36	1	Front LHS Lower Arm	Bent	\$	480.00	\$	480.00
37	1	Front Stabilizer Bar	Serviceable	\$	388.00	\$	-
38	2	Front Stabilizer Bar Bush	Necessary	\$	40.00	\$	40.00
39	1	Front LHS Stabilizer Bar Link	Affected	\$	168.50	\$	168.50
40	1	Front LHS ABS Sensor	Shorted	\$	228.80	\$	228.80

SL Auto Consultants

Accident Claims . Survey Services . Professional Advice

Add: 129 Lorong Ah Soo #05-352 Singapore 530129

Email: slautoconsultants@gmail.com / Mobile No: 90067276

41	1	Front LHS Driveshaft	Distorted	\$	1,058.10	\$	1,058.10
42	1	Front LHS Driveshaft Oil Seal	Necessary	\$	38.00	\$	38.00
43	1	Front Cross Member	Distorted	\$	1,133.00	\$	1,133.00
44	1	Steering Rack & Pinion	Distorted	\$	1,980.00	\$	1,980.00
45	1	Steering Tie-Rod End	Bent	\$	180.00	\$	180.00
Sub-total				\$	17,843.80	\$	13,240.80
Less 10%				\$	1,784.38	\$	1,324.08
Total				\$	16,059.42	\$	11,916.72

SPECIAL NETT

1	Set Front Bumper Clip	Necessary	\$	60.00	\$	40.00
2	Set Front Fender Inner Shield Clip	Necessary	\$	60.00	\$	40.00
3	1 ATF Auto Oil	Necessary	\$	180.00	\$	150.00
4	1 Front LHS Tyre (Dre-pre 20%)	Cut	\$	400.00	\$	280.00
5	1 Front LHS Sport Rim	Grazed	\$	1,000.00	\$	800.00
Sub-total			\$	1,700.00	\$	1,310.00

LABOUR

1	Towing Service	\$	180.00	\$	120.00
2	To check wiring and lighting	\$	80.00	\$	40.00
3	To remove aircon condensor and top up aircon gas	\$	150.00	\$	120.00
4	To remove and refix radiator and perform pressure test	\$	150.00	\$	80.00
5	To perform wheel alignment test	\$	150.00	\$	80.00
6	To replace and balancing front LHS sport rim and tyre	\$	80.00	\$	50.00
7	To apply anti-rust proofing on affected areas	\$	180.00	\$	100.00
8	To replace front LHS wing mirror assy	\$	150.00	\$	80.00
9	To remove and refix front LHS door mechanism from old to new	\$	180.00	\$	-
10	To perform diagnostic check for fault code and reset factory settings	\$	280.00	\$	200.00
11	To replace front LHS undercarriage damaged parts	\$	500.00	\$	380.00
12	To panel beat and replace damaged parts on affected areas	\$	2,000.00	\$	1,600.00
13	To putty and spray painting on affected areas	\$	2,000.00	\$	1,600.00
Sub-total		\$	6,080.00	\$	4,450.00
Total cost		\$	23,839.42	\$	17,676.72

SL Auto Consultants

Accident Claims . Survey Services . Professional Advice

Add: 129 Lorong Ah Soo #05-352 Singapore 530129

Email: slautoconsultants@gmail.com / Mobile No: 90067276