

ASS. REC. BY: Taughm

REF: CS/AG/123004833/Try

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SLD 2303A

Policy No. \_\_\_\_\_

Claims No. C10022196/JL

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$127K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SNJ3330J Yr Regn: 2019, 206.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Ilva Smerito C.C. 2199.

Colour: 8/ner A/C: Insured / Std / NI / NA

Sp. Reading: 54935 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNV7P4815 VAL 5599971

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/50R19

R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or HZENIS

Front 6 mm Rear 6 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. 8/5/2023 D.O.I. 28/5/23

Survey held at A-Tec

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
9/6/23	Submit preli report-revised fig \$4085 check items \$162

Date/Time, File Pass to? ☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

2) 9/6/23-typist

Rep. / Format:

Days Of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\$ + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

# A-Tec Automotive Pte Ltd

KIA SORENTO (SNJ3330J)

## ESTIMATE VEHICLE COST OF REPAIR

### List Items

No.	Description ( Parts )	Cost of Repair	
1	Front Bumper Assy	\$1,500.00 <i>Ry</i>	
2	Front Bumper Bracket LH	\$100.00 <i>X</i>	nn
3	Front Bumper Bracket RH	\$100.00 <i>X</i>	nn
4	Front Bumper Retainers LH	\$180.00 <i>?</i>	
4	Front Bumper Grille Assy	\$1,200.00 <i>X</i>	nn
4	Front Valance Panel Lower	\$300.00 <i>X</i>	nn
5	Front Bumper Trim LH	\$350.00 <i>cal</i>	
6	Front Fender LH	\$1,400.00 <i>bt</i>	
7	Front headlamp LH	\$1,800.00 <i>int</i>	
8	Front Fender Garnish LH	\$120.00 <i>X</i>	nn
9	Front wheel hub bearing LH	\$400.00 <i>X</i>	nn
10	Front wheel shock absorber LH	\$520.00 <i>X</i>	nn
11	Front Fog Lamp Trim LH	\$320.00 <i>X</i>	nn
Total Cost of List Parts		\$8,290.00	

### Special Nett Items

No.	Description ( Parts )	COST	
1	Front Bumper Clips ( 1 set )	\$250.00 <i>3000</i>	
2	Front Bumper Sensors ( 1 set )	\$600.00 <i>X</i>	nn
3	Front Wheel Tyre LH	\$250.00 <i>X</i>	nn
3	Front Wheel Sports Rim LH	\$800.00 <i>X</i>	nn
Total Cost of Special Nett Items		\$1,900.00	
TOTAL COST OF PARTS		\$10,190.00	

### Labour

No.	Description ( Parts )	COST	
1	To cut, weld, straighten affected areas and replace damaged parts.	\$1,200.00 <i>300</i>	
2	To putty and spray painting the affected areas.	\$1,200.00 <i>300</i>	
3	To check front lighting and wiring.	\$120.00 <i>30</i>	
4	To apply anti rust proofing to the affected areas.	\$250.00 <i>30</i>	
5	To remove and install front inner garnish and trim to facilitate the repair.	\$200.00 <i>X</i>	
6	To conduct vehicle full diagnosis and fault findings to facilitate the repair.	\$400.00 <i>X</i>	
7	To conduct wheel alignment	\$250.00 <i>X</i>	
Total Cost of Labour		\$3,620.00	
TOTAL COST OF REPAIR		\$13,810.00	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Taufik 97495749 / 62563561  
wp' 24/5/23 @ 1230

4/5 Resurvey after repair

Taufik @ Kantowin  
3 days

- To check consistency of accident  
- To check part prices.