



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 3304Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT RH DOOR	BENT	3,225.00	1,120.00
2	FRONT RH DOOR LOCK	DENTED	480.00	325.00
4	FRONT RH DOOR WINDOW GEAR	DISTORTED	339.00	339.00
1	FRONT RH DOOR GEAR MOTOR	JAMMED	318.90	318.90
1	FRONT RH DOOR OUTER HANDLE	SERVICEABLE	298.00	-
2	FRONT RH DOOR TRIM BOARD	MTG CRACKED	668.00	415.00
1	FRONT RH DOOR LAMP	SERVICEABLE	330.40	-
1	FRONT RH DOOR INNER RUBBER SEAL	DISTORTED	298.00	298.00
1	FRONT RH DOOR WINDOW FRAME RUBBER	SERVICEABLE	388.00	-
1	FRONT RH DOOR WINDOW CHANNEL	DISTORTED	212.00	212.00
1	FRONT RH DOOR PILLAR (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT RH DOOR FRAME (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT RH DOOR WHEELARCH GARNISH	BENT	420.00	280.00
1	FRONT RH DOOR SIDE PILLAR (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 15% DISCOUNT		-1,046.60	-496.19
			5,930.70	2,811.71
1	FRONT RH DOOR WEATHERSTRIP (\$245.60) (50%) (SN)	DISTORTED/ DENTED	385.00	122.80
	LESS 15% DISCOUNT		-57.75	-
			327.25	122.80
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT RH DOOR COMPANY STICKER (SN)	NECESSARY	800.00	250.00
			800.00	250.00
<b><u>LABOUR</u></b>				
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT RH DOOR PILLAR, FRONT RH DOOR FRAME AND FRONT RH DOOR SIDE PILLAR.		600.00	400.00
	TO TRANSFER DOOR PARTS TO ANOTHER DOOR.		120.00	60.00

Report Ref No. CS/AWA23004834/Kcy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	ANTI RUST.		120.00	30.00
	CHECK DOOR WIRING SYSTEM ETC.		90.00	20.00
	TO DO SPRAY PAINTING ON AFFECTED AREA INNER OUTER.		800.00	450.00
			1,730.00	960.00
GRAND TOTAL			8,787.95	4,144.51
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CS/AWA23004834/Kcy3m4

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.