

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	ALLIED WORLD A	SSURANCE COMPANY LTD	Ref:	CS/AWA23004834/Kcy3m4	
	(SINGAPORE BRA 60 ANSON ROAD MAPLETREE ANS SINGAPORE 079	#08-01 (8th FLOOR) ON	Date	30/06/2023	
			Code	: AWA	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YM 5370J	Veh. Inspected	YP 3304Z	
	Policy No.	BVFCSB0013662203	Coverage (\$)	0.00	
	Claim No.	NSV2300117/PC	Excess (\$)	0.00	
	Assign From	HEW LEE FONG	Assign Date	11/05/2023	
2.	2. Vehicle Particulars & Condition				
	Make & Model	ISUZU NPR75 (M)	c.c	5193	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JAANPR75HG7102394	Colour	WHITE	
	Odometer	392825 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/75 R17.5	SAILUN	9 mm	
	L/H Front Tyre	215/75 R17.5	SAILUN	9 mm	
	R/H Rear Tyre	215/75 R17.5 (D)	SAILUN	2/2 mm	
	L/H Rear Tyre	215/75 R17.5 (D)	SAILUN	2/2 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	09/05/2023	Inspection Date	30/05/2023	
	Survey held at SQM PTE LTD				
		1003 TOA PAYOH INDUSTRIAL PARK, #05-1501, TOA PAYOH INDUSTRIAL PARK, SINGAPORE 319075			
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: