



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD
C/O TOPLIS AND HARDING (S) PTE LTD
133 CECIL STREET
#17-01A
KECK SENG TOWER SINGAPORE 069535

Ref: CS/TPS23004845/Tvy3e2

Date: 21/07/2023

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EXCAVATOR BUCKET	Veh. Inspected	WD 4608C
Policy No.	A331305	Coverage (\$)	0.00
Claim No.	22/23/23/LL00/003841	Excess (\$)	0.00
Assign From	VICTOR FONG	Assign Date	11/05/2023

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI FUSO	c.c	10677
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	FS72HSA10001	Colour	WHITE / BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	LING LONG	8 mm
L/H Front Tyre	295/80 R22.5	LING LONG	8 mm
R/H Rear Tyre	295/80 R22.5 (D)	LING LONG	8/8 mm
L/H Rear Tyre	295/80 R22.5 (D)	LING LONG	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND ROOFTOP.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/05/2023	Inspection Date	15/05/2023
Survey held at	GOLDBELL ENGINEERING PTE LTD 10 TUAS AVE 18 SINGAPORE 638894		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
--	------------------------