

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FW 463E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	FRONT FORK TUBE ASSY	SERVICEABLE	880.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	280.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	150.00	-
1	SET FRONT SIGNALS	CUT	260.00	190.00
1	HANDLE BAR	BENT	280.00	180.00
1	HANDLE BAR BALANCER O/S	CUT	155.00	38.00
1	SET HAND GRIP	NOT NECESSARY	88.00	-
1	SET MIRROR	CUT	330.00	180.00
1	BRAKE LEVER	CUT	160.00	105.00
1	FOOT STEP PANEL - R/H	CUT	180.00	166.00
1	FOOT STEP LOWER PANEL - R/H	CUT	280.00	202.00
1	CENTER COVER	CUT	155.00	155.00
1	FRONT SIDE COVER	CUT	280.00	280.00
1	EXHAUST PROTECTOR FRONT	CUT	95.00	95.00
1	EXHAUST PROTECTOR REAR	сит	115.00	115.00
1	EXHAUST PROTECTOR CAP	NOT NECESSARY	105.00	-
	LESS 10% DISCOUNT		-379.30	-170.60
			3,413.70	1,535.40
	SPECIAL NETT ITEMS			
1	SET NUMBER PLATE (SN)	SERVICEABLE	38.00	-
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	BEARING CONE (SN)	NOT NECESSARY	95.00	-
1	LOGO (SN)	NECESSARY	120.00	80.00
1	REAR BOX (SN)	NOT NECESSARY	580.00	-
1	REAR BOX BRACKET (SN)	NOT NECESSARY	180.00	-
1	CRASH BAR (SN)	CUT	480.00	380.00
			1,579.00	460.00
	LABOUR			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-

Report Ref No. CS/LPC23004849/Ucy3e2



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

2,295.40

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PROVIDE LABOUR.		480.00	300.00
			560.00	300.00
	GRAND TOTAL		5,552.70	2,295.40

Report Ref No. CS/LPC23004849/Ucy3e2

CHUA KANG SENG

Licensed Appraiser