



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807			Ref: CS/MSG23004854/Kwy3m4	
			Date: 23/05/2023	
			Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	GBF 7984J	Veh. Inspected	YP 7184B
	Policy No.		Coverage (\$)	0.00
	Claim No.	594724	Excess (\$)	0.00
	Assign From	DOUGLAS ONG	Assign Date	11/05/2023
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi feb21 (M)	c.c	2998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	FEB21EA21455	Colour	WHITE
	Odometer	305870 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/85 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	195/85 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	195/85 R15 (D)	BRIDGESTONE	7/7 mm
	L/H Rear Tyre	195/85 R15 (D)	BRIDGESTONE	7/7 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	24/05/2019	Inspection Date	16/05/2023
	Survey held at	160 SIN MING AUTOCITY #02-16 SINGAPORE 575722		
	Repairer	CMK MOTOR SERVICE REPAIR		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	