ASS. REC. BY:	23004854/Km
//	
From: Date:  Estimated Cost:  OD / TP / WS / TP RES / OD RES / EVA / INV / MV  To Inspect Vehicle No: at Workshop m/s  of Insured: Policy No. Claims No. Sum Insured: Excess: (Client's Record) Make of Veh:  ////  (Policy Condition) Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value: IDAC Accident Rport: Consistent? : Yes or No	Veh No: YP 7/84 B Yr Regn: S 1 17  Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  Truck / Trailer or P / P / B / C.C. 2899  Colour White AC: Insured / Std / NI / NA  Sp.Reading 3058 fo T/Radio: Insured / Std / NI / NA  Eng/No:  C/No: PEB 21 EA 21455  Gen. Cond: Good / Fair / Poor / Burnt  Steering: Inograf / Jammed / Leaked / Burnt or  Brake: Inograf / Jammed / Leaked / Burnt or  Mod : MID S/Rim / STD A/Rim or  Tyre Size: F: PS / S / S / S / S  R:
GIA / PR Seen: Consistent?: Yes or No  Est. Repairs: G7 days Res.: Yes or No	L/Bal. 6 mm L/Bal. 7 7 mm  D.O.A. 79/5/8/9 D.O.I. 16/5/2013
CA / REV / REP. / 24 HRS  Date:Person Contacted: Vehicle: IN/OUT	Survey held at  Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date / Time   Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Immit accordingly	
17/05/2023 Submit 4/5 \$8,200.00 @ 7 days (Red \$3	300.00/29%)
11 7	survey No. of Trip: Survey Fee:
Add Fee:	: Site Insp (\$ ) _5 + RSSI
Report Format: TP	:Interview (\$ ) Firsts
Lump Sum / I.B.I: (\$ \$6,200	Tech Invs (\$ ) Others  Weekend (\$ )
p " = 1	107AL

Insurance Loss Adjusters and Licensed Appraiser Regn. 652868584L
Blk 131 Rivervale Street #05-872 S'pore 540131 Tel:65528323 Fax:64574321

Our ref: PS/031/05/19 Date: 20th June 2019

M/s Green City-Scape Pte Ltd c/o 160 Sin Ming Drive #08-11 Sin Ming Auto City Singapore 575722

Dear Sir,

Re: THIRD PARTY CLAIM

We refer to your instruction to appraise the vehicle YP 7184 B on 29th May 2019.

A static inspection was conducted during our survey and our report is enclosed for your perusal. The estimated repair cost submitted by **Messrs. CMK Motor Service Repair** for \$17,480.80 as per our attached schedule have been inspected thoroughly each and every item and revised by us against the actual damages found on the vehicle which have been recommended by us accordingly.

The repairer has agreed to undertake repairs at our revised amount of \$11,500.00 lump sum corresponding to supply of parts, labour charges and spray-painting. However, we have not given instruction to authorize the repairs.

Under normal circumstances, the estimated period of repairs would be **SEVEN** (7) days. Photographs of the damaged vehicle taken by us during our inspection are enclosed.

We are reverting the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services.

Yours faithfully,

PRESTIGE APPRAISER SERVICES

LOUIS S C NG CAE AMIMI Dip. MTM. Automotive Engineer Licensed Appraiser

Encl.

A SECULIAR SECULIAR

#### VEHICLE INSPECTION REPORT

To: M/s Green City-Scape Pte Ltd

c/o 160 Sin Ming Drive #08-11 Sin Ming Auto City

Singapore 575722

Date

: 20th June 2019

Our Ref : PS/031/05/19
Policy No :

Sum Insured : Excess : T/P Claim

Assigned By : M/s Green City-Scape Pte Ltd
Assignment Date : 29th May 2019
Accident Date : 24th May 2019
Inspection Date : 29th May 2019
Workshop Name : CMK Motor Service Repair

Survey Conducted At : 160 Sin Ming Drive

#08-11 Sin Ming Auto City

Singapore 575722

#### PARTICULARS OF VEHICLE

Registration No

: YP 7184 B

Colour

Make/Model : Mitsubishi FEB21 Type Of Body : Lorry (Metal Body)

Mileage : 84797km
Engine No : HIDDEN
Chassis No : FEB21EA21455
Max. Laden Wt. : 5000kg

Year Of Manu./Regn. : -

: White

Others

CONDITION OF TYRES

R/H SIDE

L/H SIDE

5mm 195/85R15 Bridgestone 5mm 195/85R15 Bridgestone

Front Tyre : 5mm 195/85R15 Bridgestone Rear Tyre (inner) : 5mm 195/85R15 Bridgestone Rear Tyre (outer) : 5mm 195/85R15 Bridgestone

5mm 195/85R15 Bridgestone

The above represent the estimated remaining life of the tyre treads.

### PRE-ACCIDENT CONDITION (Static tests only)

Handbrake

: Serviceable

Paint Work : Good
Others

Footbrake

: Serviceable

Steering

: Serviceable

#### POINT OF IMPACT

The vehicle sustained impacts on the front & L/H portion.

#### GENERAL DESCRIPTION OF DAMAGES

The front panel, bumper, L/H corner panel, door, door pillar were dented/distorted.

For details of damages please refer to schedule attached.

## **REMARKS:**

This survey was conducted strictly without prejudice.

Contract Contract

Vehicl	e No: YP 7184 B			Our Ref:		PS/031/05/19
Qty	Descriptions	Conditions		Repairer's Est.		Our Revised.
1	front bumper 1610 · 33	dented	\$	1,204.80	\$	1,204.80
1	front bumper bracket	dented	Φ	82.00	φ	82.00
1	L/H front bumper side	missing/dislodged		163.00		163.00
1	R/H front bumper side	serviceable		163.00		103.00
1	R/H front bumper bracket	dented - repair		82.00		-
1	front grille	missing/dislodged		698.50		698.50
1	front grille bracket	dented		62.30		62.30
1	front grille emblem	necessary		102.10		102.10
6	front grille clip	necessary		30.00		30.00
1	front panel	dented/distorted		1,055.20		1,055.20
1	front wiper panel	dented/cracked		655.30		655.30
1	L/H corner panel	dented		449.20		449.20
1	L/H door	dented/distorted		1,889.40		1,889.40
1	L/H door weatherstrip	distorted		218.50	A	13 218.50 X
2	L/H door hinge	dented		368.20		n 368.20 X
1	L/H mirror	dented/cut		298.50		298.50
1	L/H mirror stay	dented		352.20		n 352.20 K
1	L/H headlamp	broken		693.00		693.00
1	R/H headlamp	holder cracked		693.00		693.00
1	L/H sidelamp	broken		198.50		198.50
1	L/H front signal lamp	broken		286.00		286.00
1	L/H front step garnish	dented/cut		295.20	/	~B 295.20 X
1	L/H front wheel arch garnish	dented/cut		186.00		NR 186.00 X
1	L/H front mudguard	dented/cut		210.20		210.20 X
1	aircon evaporator unit	holder cracked		985.60		985.60
1	aircon centre duct	holder fractured		687.40		687.40
1	front windscreen weatherstrip	distorted		222.10		222.10 50 lsw
1	L/H front door pillar	dented - repair		689.60		222.10 - 0 : 02
	ETT HORE GOOF Pillar	derited repair		13,020.80		12,086.20
		Less 10%		10,020.00		1,208.62
		153	\$	13,020.80	\$	10,877.58
	Labour Charges & Misc	00%	•	10,020.00	*	
	To dismantle & replace damaged parts,	panel beat where				
	necessary.			1,600.00		1,300.00 900
,				-		
	To putty, apply primer & spray-paint on the affected portion.			1,200.00		1,000.00 9001
	To apply rust-proofing on repaired, replaced panel.			150.00		120.00 69
	To remove/refit front windscreen glass to facilitate repairs.			160.00		120.00 801
	To remove/renew aircon evaporator unit.			200.00		150.00
	To remove/refit dashboard to facilitate repairs.			300.00		240.00
	To remove/transfer L/H door mechanisms.			180.00		150.00 60
	To redraw logo & rewrite lettering			600.00		400.00 250/
	To check wiring functions.			70.00		50.00 201
	TO OHEON WITHING TUTIONOTIS.		\$	17,480.80	\$	14,407.58

The state of the s

Vehicle No: YP 7184 B

Our Ref:

PS/031/05/19

Qty

Descriptions

Conditions

Repairer's Est.

Our Revised.

Note: The repairer has agreed to undertake the repairs at our adjusted amount of \$11,500.00 lump sum corresponding to

supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period

would be SEVEN (7) days.

Pursuant to your instruction we have **not** authorised repairs

on your behalf.

PRESTIGE APPRAISER SERVICES

LOUIS S C NG CAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer