



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL  
(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRESINGAPORE  
239924

Ref: CS/AGI23004861/Kqy3e2

Date: 05/06/2023

Code: AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |                |                       |            |
|---------------------|----------------|-----------------------|------------|
| <b>Insured Veh.</b> | SKW 7387L      | <b>Veh. Inspected</b> | SMR 5586U  |
| <b>Policy No.</b>   | P10095434R04   | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | C10022233/CD   | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | FRAULEINE KHOO | <b>Assign Date</b>    | 12/05/2023 |

### 2. Vehicle Particulars & Condition

|                         |                   |                     |                    |
|-------------------------|-------------------|---------------------|--------------------|
| <b>Make &amp; Model</b> | HYUNDAI IONIQ (A) | <b>c.c</b>          | 1580               |
| <b>Engine No.</b>       | HIDDEN            | <b>Year of Reg.</b> | 2020               |
| <b>Chassis No.</b>      | KMHC851CVLU201249 | <b>Colour</b>       | WHITE              |
| <b>Odometer</b>         | 243543 KM         | <b>Steering</b>     | IN ORDER           |
| <b>Brakes</b>           | IN ORDER          | <b>Modification</b> | STANDARD ALLOY RIM |
| <b>General</b>          | GOOD              |                     |                    |

### 3. Conditions of Tyres

|                       | Size       | Make  | Balance |
|-----------------------|------------|-------|---------|
| <b>R/H Front Tyre</b> | 195/65 R15 | WANLI | 9 mm    |
| <b>L/H Front Tyre</b> | 195/65 R15 | WANLI | 9 mm    |
| <b>R/H Rear Tyre</b>  | 195/65 R15 | WANLI | 8 mm    |
| <b>L/H Rear Tyre</b>  | 195/65 R15 | WANLI | 8 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

|                       |  |                        |            |
|-----------------------|--|------------------------|------------|
| <b>Accident Date</b>  | 10/05/2023   | <b>Inspection Date</b> | 12/05/2023 |
| <b>Survey held at</b> | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                        |            |

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**