

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI23004873/AVY3Q2
Date: 31/05/2023**REFERENCE**

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMY6079Z	Insured Vehicle No :	YQ5349G
Date of Loss:	06/05/2023	Nature of Claim:	TP
		Claim No:	CDMCG23001120

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY6079Z	Engine No:	HRA2405181A
Make & Model:	NISSAN QASHQAI, 1.2 (A)	Chassis No:	SJNFEAJ11U1915749
Reg. Date:	07/07/2017 (Man. Year: 2017)	Odometer:	97256 km
Colour:	White		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,247.10	5,337.98	1,909.12	26.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,660.00	1,290.00	43.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,197.10	6,997.98	3,199.12	31.37
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	10,197.10	5,500.00	4,697.10	46.06

INSPECTION

Date of Assignment:	12/05/2023		
Date Inspected:	12/05/2023	Inspected At:	1 KAKI BUKIT AVE 6 #01-82 AUTOBAY SINGAPORE 417883 Repairer:Sin Yu Sin Workshop (HQ)
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2023)
Parts: M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMY6079Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	755.40 FL	*755.40 FL
2	1		*REAR BUMPER SIDE HOLDER	Damaged	35.90 FL	*35.90 FL
3	1		*TAILLAMP	Cracked	323.70 FL	*323.70 FL
4	1		*TAILLAMP PANEL	Repair	192.30 FL	*- FL
5	1		*REAR FENDER	Distorted	1,081.40 FL	*1,081.40 FL
6	1		*REAR FENDER ARC GARNISH	Cut	483.10 FL	*483.10 FL
7	1		*REAR FENDER INNER TRIM BOARD	Not Necessary	361.70 FL	*- FL
8	1		*REAR FENDER INNER SHIELD	Torn	202.10 FL	*202.10 FL
9	1		*REAR FENDER AIR VENT	Cracked	62.80 FL	*62.80 FL
10	1		*REAR DOOR	Dented	1,166.40 FL	*1,166.40 FL
11	1		*REAR DOOR LOCK	Damaged	196.70 FL	*196.70 FL
12	1		*REAR DOOR WEATHERSTRIPE	Not Necessary	187.40 FL	*- FL
13	1		*REAR DOOR INNER TRIM BOARD	Cracked	844.40 FL	*844.40 FL
14	1		*REAR DOOR GLASS REGULATOR C/W MOTOR	Damaged	487.90 FL	*487.90 FL
15	1		*REAR ALARM	Cracked	102.40 FL	*102.40 FL
16	1		*TAILGATE REFLECTOR	Not Necessary	235.40 FL	*- FL
17	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
18	1		*SET REAR FENDER ARC GARNISH	Necessary	20.00 FS	*20.00 FS
19	1		*SET REAR FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
20	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
21	1		*REAR DOOR BLACK TAPE	Necessary	60.00 FS	*60.00 FS
22	1		*REAR WHEEL RIM	Not Necessary	780.00 FS	*- FS
23	1		*REAR TYRE	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,919.00	5,912.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	671.90	574.22
Total Parts (\$\$)	7,247.10	5,337.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	1,200.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	600.00
3	WIRING CHECK	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO TRANSFER DOOR FITTINGS	New	150.00	60.00
7	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
8	TO REMOVE REVERSE SENSOR	New	100.00	50.00
			Gross Labour Cost (S\$)	2,950.00
				1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >