



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 6065M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR O/S DOOR	BENT	1,085.70	1,011.50
1	REAR O/S DOOR INNER LOCK	TO REPAIR SEE LABOUR	387.20	-
1	REAR O/S DOOR RUBBER	SERVICEABLE	186.20	-
1	REAR O/S DOOR INNER TRIM BOARD	SERVICEABLE	455.70	-
1	REAR O/S FENDER	BENT	725.60	690.95
1	REAR BUMPER	MTG CRACKED	650.90	650.90
1	REAR O/S BUMPER SIDE RETAINER	SERVICEABLE	65.70	-
1	REAR O/S FENDER INNER SHIELD	SERVICEABLE	87.50	-
1	REAR O/S SHOCK ABSORBER	SERVICEABLE	387.60	-
1	REAR O/S HUB ASSY	BENT	405.10	245.00
1	REAR O/S HUB BEARING	NECESSARY	255.70	108.00
1	REAR AXLE ASSY	SERVICEABLE	1,250.70	-
	LESS 15% DISCOUNT		-891.54	-405.95
			5,052.06	2,300.40
<u>SPECIAL NETT ITEMS</u>				
1	O/S ROCKER PANEL GARNISH (STICKER ONLY) (SN) (LOCAL REPAIR)	NECESSARY	550.00	180.00
1	CAR BODY STICKER (SN)	NECESSARY	1,000.00	750.00
1	REAR O/S TYRE RIM (SN)	DENTED	480.00	280.00
20	CLIP @\$2.00 (SN)	NECESSARY	40.00	40.00
			2,070.00	1,250.00
<u>LABOUR</u>				
	REMOVE / RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING ETC. INCLUSIVE OF THE REPAIR OF REAR O/S DOOR INNER LOCK.		1,200.00	700.00
	TO PUTTY AND SPRAY PAINT.		1,000.00	600.00
	CHECK & RECONNECT WIRING.		40.00	20.00
	TO RESPRAY ANTI-RUST PROOFING TREATMENT.		150.00	60.00
	REMOVE / REFIT FUEL TANK TO FACILITATE REPAIR.	NOT NECESSARY	80.00	-
	REMOVE / REFIT ROOF LINING TO FACILITATE REPAIR ON REAR FENDER.		200.00	100.00

Report Ref No. CS/AGI23004883/Kqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK & REALIGN WHEEL ALIGNMENT.		80.00	60.00
	DIAGNOSTIC CHECK ON REAR UNDERCARRIAGES.		180.00	50.00
			2,930.00	1,590.00
GRAND TOTAL			10,052.06	5,140.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CS/AGI23004883/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.