

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123004884/UQY3Q2**Date:** 19/06/2023REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG22010666
Claimant Vehicle No :	FBN1336C	Insured Vehicle No :	GBB5035H
Date of Loss:	30/04/2023	Nature of Claim:	TP
		Claim No:	CDMCG23001146

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN1336C	Engine No:	G3H6E0014535
Make & Model:	YAMAHA NMAX155, 155cc ABS	Chassis No:	MH3SG431000011702
Reg. Date:	10/09/2019 (Man. Year: 2019)	Odometer:	91561 km
Colour:	White		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110-70-13	Rear Tyre Size:	130-70-13
Front Left Side:	Timsun 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	809.00	613.00	196.00	24.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	630.00	20.00	3.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,459.00	1,243.00	216.00	14.80
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	1,459.00	1,000.00	459.00	31.46
+ GST 8.00/8.00% (S\$)	116.72	80.00	36.72	31.46
Nett Amount (S\$)	1,575.72	1,080.00	495.72	31.46

INSPECTION

Date of Assignment:	12/05/2023	Ban Hock Hin Co. Pte Ltd (HQ)
Date Inspected:	15/05/2023 Inspected At:	BLK 8 Defu South Street 1, #04-28 JTC Defu Industrial City
Estimated Period of Repair:	4.0 days	Singapore 533758

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Jun 2023)	
Parts:	N/A	YAMAHA NMAX155 155cc ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN1336C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BELLY PAN	Cut	38.00 F	*38.00 FL
2	1		*BOARD FOOTREST LH	Scratched	59.00 F	*59.00 FL
3	1		*BOX FILTER AIR OUTER (Scratched)	Not Consistent With The Impact	20.00 F	*- FL
4	1		*COVER SIDE LH (GREY)	Cracked	42.00 F	*42.00 FL
5	1		*COVER SIDE LOWER LH (WHITE)	Cracked	25.00 F	*25.00 FL
6	1		*COVER SIDE LOWER RH (WHITE)	Cut	25.00 F	*25.00 FL
7	1		*COVER SIDE REAR RH (WHITE)	Cracked	33.00 F	*33.00 FL
8	1		*COWLING FRONT LH (WHITE)	Cut	36.00 F	*36.00 FL
9	1		*COWLING FRONT RH (WHITE)	Cut	36.00 F	*36.00 FL
10	2		*EMBLEM (YAMAHA) LOGO	Necessary	34.00 F	*34.00 FL
11	1		*MUDGUARD FRONT (WHITE)	Grazed	52.00 F	*52.00 FL
12	1		*PANEL 1 (GREY) LH	Cut	25.00 F	*25.00 FL
13	1		*PANEL 2 (GREY) RH	Cut	25.00 F	*25.00 FL
14	1		*SCREW (VISOR)	Not Necessary	3.00 F	*- FL
15	2		*STICKER (CERTIS CISCO) LOGO NEW MODEL LH /RH	Necessary	48.00 FS	*48.00 FS
16	1		*STICKER (CERTIS CISCO) WINDSHIELD NEW MODEL (Not Necessary)	Not Consistent With The Impact	65.00 FS	*- FS
17	1		*STICKER (CISCO) COVER CENTRE LH	Necessary	40.00 FS	*40.00 FS
18	1		*STICKER (CISCO) CCOWLING FRONT LH	Necessary	40.00 FS	*40.00 FS
19	1		*STICKER (CISCO) CCOWLING FRONT RH	Necessary	40.00 FS	*40.00 FS
20	1		*STICKER (CISCO) LINING COVER REAR LH	Necessary	18.00 FS	*18.00 FS
21	1		*STICKER (CISCO) MUDGUARD FRONT	Necessary	40.00 FS	*40.00 FS
22	1		*WINDSHIELD (Cracked)	Not Consistent With The Impact	65.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	809.00	656.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	43.00
Total Parts (\$\$)	809.00	613.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT CHARGES	New	50.00	35.00
2	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	175.00	170.00
3	SPRAY LACQUER ON COVER CENTRE LH	New	100.00	100.00
4	SPRAY LACQUER ON COVER SIDE REAR RH	New	70.00	70.00
5	SPRAY LACQUER ON COWLING FRONT LH	New	100.00	100.00
6	SPRAY LACQUER ON COWLING FRONT RH	New	100.00	100.00
7	SPRAY LACQUER ON MUDGUARD FRONT	New	55.00	55.00
Gross Labour Cost (S\$)			650.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >