

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23004892/APA3Q2**Date:** 20/07/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002833297
Claimant Vehicle No :	SKW6777B	Insured Vehicle No :	SFL7373T
Date of Loss:	25/04/2023	Nature of Claim:	TP
		Claim No:	202332007642

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW6777B		
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Engine No:	2ZR1665026
Reg. Date:	11/11/2015 (Man. Year: 2015)	Chassis No:	JTDGG20W60J003098
Colour:	Bronze	Odometer:	203472 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,168.07	3,976.55	11,191.52	73.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,610.00	1,970.00	640.00	24.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,778.07	5,946.55	11,831.52	66.55
Approved Total (Overridden) (S\$)		4,600.00		
Nett Amount (S\$)	17,778.07	4,600.00	13,178.07	74.13
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		5,186.75		
Global Sum Settlement (S\$)		5,100.00		

INSPECTION

Date of Assignment:	12/05/2023	
Date Inspected:	16/05/2023 Inspected At:	F-1 Autoclinic Pte Ltd - Block 25 Kaki Bukit (HQ) BLOCK 25 KAKI BUKIT ROAD 4, #05-26 SYNERGY @ KB Singapore 417800
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jul 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW6777B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,558.00 F	*1,280.00 FL
2	2		*REAR BOOT LID HINGES	Not Necessary	422.00 F	*- FL
3	1		*REAR BOOT LID EMBLE LOGO	Necessary	85.00 F	*85.00 FL
4	1		*REAR BOOT LID RH LOGO	Necessary	50.00 F	*50.00 FL
5	1		*REAR BOOT LID INNER LOCK	Damaged	549.10 F	*348.00 FL
6	1		*REAR BOOT LID INNER RUBBER	Cut	255.00 F	*255.00 FL
7	1		*REAR BOOT LID CENTER MOULDING	Cracked	352.00 F	*352.00 FL
8	2		*REAR BOOT LID CENTER MOULDING SIDE CLIPS	Necessary	17.00 F	*17.00 FL
9	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
10	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	310.20 F	*- FL
11	1		*REAR BOOT LID INNER TRIM BOARD	Creased	658.00 F	*485.00 FL
12	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	188.00 F	*188.00 FL
13	1		*REAR BOOT LID SIDE REFLECTOR	N/S Cracked	842.40 F	*277.00 FL
14	2		*TAIL LAMP	Not Necessary	1,450.00 F	*- FL
15	4		*TAIL LAMP CLIPS	Not Necessary	34.00 F	*- FL
16	2		*TAIL LAMP PANEL	Not Necessary	622.40 F	*- FL
17	1		*REAR END PANEL OUTER	Dented	740.00 F	*597.00 FL
18	1		*REAR END PANEL INNER	Repair	580.00 F	*- FL
19	1		*REAR END PANEL TOP GARNISH	Deformed	288.20 F	*288.20 FL
20	1		*REAR BUMPER	Deformed	1,377.00 F	*688.00 FL
21	1		*REAR BUMPER SIDE REFLECTOR	N/S Cracked	190.40 F	*95.20 FL
22	2		*REAR BUMPER SIDE BRACKET	Not Necessary	224.20 F	*- FL
23	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
24	2		*REAR BUMPER BRACKET	Not Necessary	196.40 F	*- FL
25	8		*REAR BUMPER CLIPS	Necessary	52.00 F	*30.00 FL
26	2		*REAR FENDER INNER LINER COVER	Not Necessary	976.00 F	*- FL
27	2		*REAR FENDER INNER PANEL	Not Necessary	1,310.00 F	*- FL
28	1		*REAR FLOOR PANEL TOP COVER	Not Necessary	535.77 F	*- FL
29	1		*REAR FLOOR PANEL SEALANT	Not Necessary	250.00 F	*- FL
30	1		*REAR FLOOR PANEL INNER TRIM	Not Necessary	655.00 F	*- FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					15,168.07	5,235.40
- List Item Discount on L Items 0.00/25.00% (\$\$)					0.00	1,258.85
Total Parts (\$\$)					15,168.07	3,976.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION	New	120.00	60.00
2	TO REMOVE & REFIX REAR EXHAUST (NPA)	New	0.00	0.00
3	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
4	GUM	New	50.00	50.00
5	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
6	TO REMOVE & REFIX REAR CAMERA (NPA)	New	0.00	0.00
7	TUFF KOTE	New	120.00	60.00
8	TO CHECK WIRING SYSTEM	New	80.00	30.00
9	PANEL BEATING	New	1,000.00	800.00
10	SPRAY PAINTING	New	1,000.00	800.00
Gross Labour Cost (S\$)			2,610.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >