

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23004916/KYA3Q2**Date:** 31/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210085861
Claimant Vehicle No :	SMW6584S	Insured Vehicle No :	GBK5515S
Date of Loss:	12/05/2023	Nature of Claim:	TP
		Claim No:	5128035287SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW6584S	Engine No:	2ZR2G76846
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU703091278
Reg. Date:	30/11/2020 (Man. Year: 2020)	Odometer:	185427 km
Colour:	Metallic Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Trangle 2 mm	Rear Left Side:	Falken 3 mm
Front Right Side:	Trangle 2 mm	Rear Right Side:	Falken 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,828.00	2,483.40	344.60	12.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	530.00	270.00	33.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,628.00	3,013.40	614.60	16.94
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	3,628.00	2,400.00	1,228.00	33.85
+ GST 8.00/8.00% (S\$)	290.24	192.00	98.24	33.85
Nett Amount (S\$)	3,918.24	2,592.00	1,326.24	33.85
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,994.00		

INSPECTION

Date of Assignment:	15/05/2023	Optima Werkz Pte Ltd (HQ)
Date Inspected:	15/05/2023 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
		Autopoint
		Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SIDE MIRROR ASSY LH	Broken	1,283.00 FL	*1,283.00 FL
2	1		*FRONT SIDE MIRROR COVER LH	Missing	99.00 FL	*99.00 FL
3	1		*FRONT DOOR LH	Bent / Warped	1,249.00 FL	*1,249.00 FL
4	1		*FRONT DOOR WINDOW GLASS	Missing	879.00 FL	*581.20 FL
5	1		*FRONT DOOR OUTER LOWER MOULDING LH	Dented	99.00 FL	*99.00 FL
6	1		*FRONT DOOR HANDLE LH	Repair	95.00 FL	*- FL
7	1		*FRONT FENDER RH (NPA)	Repair	0.00 FL	*- FL
8	1		*FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,754.00	3,311.20
- List Item Discount on L Items 25.00/25.00% (S\$)	926.00	827.80
Total Parts (S\$)	2,828.00	2,483.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST FRONT ACCIDENT AREAS & ETC	New	300.00	200.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH ,SIDE MIRROR COVER LH & ETC	New	300.00	250.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC .TO EFFECT REPLACE OF FRONT DORO LH	New	120.00	60.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	20.00
Gross Labour Cost (\$\$)			800.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >