

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI23004931/UQP3Q2**Date:** 31/07/2023**REFERENCE**

Insured/Claimant: CHUANG XIN ENGINEERING PTE LTD Policy No: DMCVSNW0001382300  
Date of Loss: 10/05/2023 Nature of Claim: OD Claim No: SNM23D203334/C01/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBJ1345Y**  
Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2836991  
Reg. Date: 09/01/2019 (Man. Year: 2018) Chassis No: JTFAT35Y40K212259  
Colour: Silver Odometer: 235611 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: S\$72,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195 R15 Rear Tyre Size: 155 R12 (D)  
Front Left Side: Habilead 2 mm Rear Left Side: Habilead 3/3 mm  
Front Right Side: Habilead 2 mm Rear Right Side: Habilead 4/4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,620.00	2,115.00	2,505.00	54.22
Miscellaneous Items	110.00	110.00	0.00	0.00
Labour	1,520.98	1,494.23	26.75	1.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,250.98</b>	<b>3,719.23</b>	<b>2,531.75</b>	<b>40.50</b>
<b>- Excess (S\$)</b>	0.00	350.00	-350.00	
<b>(S\$)</b>	6,250.98	3,369.23	2,881.75	46.10
<b>+ GST 8.00/8.00% (S\$)</b>	500.08	269.54	230.54	46.10
<b>Nett Amount (S\$)</b>	<b>6,751.06</b>	<b>3,638.77</b>	<b>3,112.29</b>	<b>46.10</b>

**INSPECTION**

Date of Assignment: 12/05/2023 Present Location: SME Motor Pte Ltd (Kaki Bukit)  
Date Inspected: 17/05/2023 Inspected At: SME Motor Pte Ltd (Kaki Bukit)  
1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit  
Singapore 417883  
Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Jul 2023)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ1345Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		4,620.00 F	*2,115.00 F
F=Franchise part.						
				Total Parts (S\$)	4,620.00	2,115.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	110.00	110.00
Sub Total (\$\$)			110.00	110.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	877.80	877.80
2	SPRAY PAINTING	New	643.18	616.43
Gross Labour Cost (\$\$)			1,520.98	1,494.23

Report was unsubmitted during this print-out.

< END OF ESTIMATES >