# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Tan Kah Leong Date: 18 May 2023

## **Preliminary Advice**

Vehicle No : GBJ1345Y Accident Date : 10/05/2023

Make : TOYOTA DYNA 150 Policy No.

DMCVSNW0001382300

Date of Inspection : 17/05/2023 Est. Duration of Repair : 5

Inspection At : SME MOTOR PTE LTD (KAKI BUKIT)

1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

#### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,250.98
Revised Amount	:S\$	3,040.98
Check Items (Estimated)	:S\$	705.00
Total	:S\$	3,745.98

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value	:S\$
-------------------	------

Pre-Accident Value :S\$ 72,000.00
COE / PARF Rebate :S\$ 13,323.00
Salvage Value :S\$

Margin for Repair :S\$ 58,677.00

### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindle	У
	let us have your authorisation.	

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments: CONDITION OF FRONT TYRES STILL WITHIN THE LEGAL REQUIREMENT AND DID NOT CONTRIBUTION TO THE ACCIDENT. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.