

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23004936/RVP3E2**Date:** 27/06/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00278322200

**Claimant Vehicle
No :** SMG2829Y**Insured Vehicle
No :** SNH180E

Date of Loss: 06/05/2023

Nature of Claim: TP

Claim
No: SNM23D203401/C03/TOHHSDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMG2829Y**Make & Model: VOLKSWAGEN TIGUAN, 1.4 HIGHLINE 280 TSI
(A)

Engine No: CZE386402

Reg. Date: 13/12/2018 (Man. Year: 2018)

Chassis No: WVGZZZ5NZJW966283

Colour: White

Odometer: 41970 km

Engine Capacity: 1395 cc

Market Value/New Car
Price: N/ASum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:CONDITION OF TYRESFront Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,155.51	7,426.31	1,729.20	18.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,990.00	5,450.00	4,540.00	45.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	19,145.51	12,876.31	6,269.20	32.75
+ GST 8.00/8.00% (\$\$)	1,531.64	1,030.10	501.54	32.75
Nett Amount (\$\$)	20,677.15	13,906.41	6,770.74	32.75

INSPECTION

Date of Assignment: 15/05/2023

Date Inspected: 16/05/2023

Inspected At:

Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2023)
Parts:	M1-SUV	VOLKSWAGEN TIGUAN 1.4 HIGHLINE 280 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG2829Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID	Bent	3,187.75 FS	*3,187.75 FS
2	2		*1K WINDOW ADHESIVE	Necessary	101.46 FS	*101.46 FS
3	1		*ALL PURPOSE CLEANER	Necessary	84.67 FS	*84.67 FS
4	1		*PRIMER	Necessary	24.91 FS	*24.91 FS
5	1		*ACTIVATOR	Necessary	21.62 FS	*21.62 FS
6	2		*APPLICATOR	Necessary	18.38 FS	*18.38 FS
7	1		*PACKING ADHESIVE REAR NUMBER PLATE PACKING	Necessary	33.08 FS	*33.08 FS
8	2		*RIVETTED CAP NUT	Necessary	5.62 FS	*5.62 FS
9	1		*HOOD LATCH BOOT LID LOCK	Not Necessary	208.85 FS	*- FS
10	1		*VW SIGN BLACK HIGH GLOSS/	Necessary	115.81 FS	*115.81 FS
11	1		*INSCRIPTION BRIGHT CHROME NAME PLATE - TIGUAN	Necessary	109.27 FS	*109.27 FS
12	1		*ADDITIONAL BRAKE LIGHT WI 3RD BRAKE LIGHT	Necessary	187.90 FS	*187.90 FS
13	1		*COVER FOR BUMPER PRIMER REAR BUMPER (UPPER)	Deformed	1,728.77 FS	*1,728.77 FS
14	1		*SENSOR BRACKET	Necessary	15.49 FS	*15.49 FS
15	1		*SENSOR BRACKET	Necessary	15.49 FS	*15.49 FS
16	1		*SPOILER SATIN BLACK REAR BUMPER (CTR)	Deformed	428.85 FS	*428.85 FS
17	1		*REAR DIFFUSOR GRANITE GRE REAR BUMPER (LOWER)	Scratched	600.57 FS	*600.57 FS
18	1		*SENSOR BRACKET	Necessary	15.49 FS	*15.49 FS
19	1		*SENSOR BRACKET	Necessary	15.49 FS	*15.49 FS
20	1		*SENSOR BRACKET	Necessary	15.49 FS	*15.49 FS
21	1		*SENSOR BRACKET	Necessary	15.49 FS	*15.49 FS
22	1		*SENSOR PRIMER	Not Necessary	194.63 FS	*- FS
23	1		*SEAL RING SATIN BLACK	Necessary	6.10 FS	*6.10 FS
24	1		*2K-PLASTIC ADHESIVE	Necessary	84.64 FS	*84.64 FS
25	1		*BONDING AGENT FOR PLASTIC	Necessary	74.37 FS	*74.37 FS
26	1		*DECORATIVE MOULDING BRIGH BUMPER LOWER MLDG CHROM (CTR)	Cracked	244.73 FS	*244.73 FS
27	1		*DECORATIVE MOULDING BRIGH BUMPER LOWER MLDG CHROME (LH)	Cracked	188.34 FS	*188.34 FS
28	1		*REFLECTOR LHS REFLECTOR INNER	Cracked	86.53 FS	*86.53 FS
29	1		*REFLECTOR LHS REFLECTOR OUTER	Not Necessary	86.53 FS	*- FS
30	1		*BUMPER REINFORCEMENT	Not Necessary	905.28 FS	*- FS
31	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	84.67 FS	*- FS
32	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	62.31 FS	*- FS
33	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Not Necessary	62.31 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	62.31 FS	*- FS
35	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	62.31 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					9,155.51	7,426.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	LABOUR	New	4,200.00	1,680.00
3	SPRAY PAINT	New	3,200.00	1,600.00
4	R&R REAR W/SCREEN	New	840.00	840.00
5	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
6	REAR WATER LEAK TEST	New	150.00	150.00
7	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
Gross Labour Cost (\$\$)			9,990.00	5,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >