

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23004939/KVP3E2**Date:** 03/07/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00016232200
Claimant Vehicle No :	SLJ9310B	Insured Vehicle No :	SLN6292T
Date of Loss:	10/05/2023	Nature of Claim:	TP
		Claim No:	SNM23D203369/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ9310B	Engine No:	CZC138695
Make & Model:	VOLKSWAGEN GOLF, 1.2 (A7) TSI (A)	Chassis No:	WVWZZZAUZHW046911
Reg. Date:	30/12/2016 (Man. Year: 2016)	Odometer:	96079 km
Colour:	Red		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 8 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,823.40	4,155.00	1,668.40	28.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	1,340.00	300.00	18.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,463.40	5,495.00	1,968.40	26.37
Approved Total (Overridden) (S\$)		4,650.00		
(S\$)	7,463.40	4,650.00	2,813.40	37.70
+ GST 8.00/8.00% (S\$)	597.07	372.00	225.07	37.70
Nett Amount (S\$)	8,060.47	5,022.00	3,038.47	37.70

INSPECTION

Date of Assignment:	15/05/2023	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	01/06/2023	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2023)
Parts:	144	VOLKSWAGEN GOLF 1.2 (A7) TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ9310B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc front bumper	Buckled / Dented	580.00 F	*580.00 F
2	1		*1 pc front bumper LH fog lamp	Serviceable	150.00 F	*- F
3	1		*1 pc front bumper LH side retainer	Distorted	25.00 F	*25.00 F
4	1		*1 pc front bumper LH parking sensor	Serviceable	115.00 F	*- F
5	1		*1 pc front LH headlamp	Cut	650.00 F	*650.00 F
6	1		*1 pc front LH fender	Bent	290.00 F	*290.00 F
7	1		*1 pc front LH fender mounting bracket	Serviceable	24.00 F	*- F
8	1		*1 pc frt LH shock absorber	Serviceable	180.00 F	*- F
9	1		*1 pc frt LH knuckle arm	Serviceable	450.00 F	*- F
10	1		*1 pc frt LH wheel hub bearing	Not Necessary	220.00 F	*- F
11	1		*1 pc frt LH sport rim	Dented	780.00 F	*780.00 F
12	1		*1 pc frt RH sport rim	Dented	780.00 F	*780.00 F
13	1		*1 pc frt RH shock absorber	Bent	180.00 F	*180.00 F
14	1		*1 pc frt RH knuckle arm	Bent	450.00 F	*450.00 F
15	1		*1 pc frt RH wheel bearing	Necessary	220.00 F	*220.00 F
16	1		*1 pc frt RH lower arm	Distorted	200.00 F	*200.00 F

F=Franchise part.

Sub Total (S\$)	5,294.00	4,155.00
+ Margin on L,N Items 10.00/0.00% (S\$)	529.40	0.00
Total Parts (S\$)	5,823.40	4,155.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	1) TO REMOVE AND REFIX FRT BUMPER, HEADLAMP, FRT LH FENDER, SIDE MIRROR, KNOCK AND REPAIR FRT LH DOOR AND RE-ALIGN TO SAME	New	500.00	450.00
2	2) TO PUTTY AND RESPRAY ON FRT BUMPER, FRT LH FENDRE, FRT LH DOOR	New	700.00	600.00
3	3) TO REMOVE AND REFIX FRT LH AND RH UNDERCARRAIGE	New	350.00	200.00
4	4) TO RUSTPROOFING	New	30.00	30.00
5	5) TO CONDUCT COMPUTERISED WHEEL ALINGMENT	New	60.00	60.00
Gross Labour Cost (\$\$)			1,640.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >